

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23004942/UVP3Q2**Date:** 07/06/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00021402200
Claimant Vehicle No :	SCL9888Y	Insured Vehicle No :	SNH5739L
Date of Loss:	10/05/2023	Nature of Claim:	TP
		Claim No:	SNM23D203373/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCL9888Y	Engine No:	1ZRX505976
Make & Model:	TOYOTA COROLLA, 1.6 (A)	Chassis No:	MR053REH104532066
Reg. Date:	23/04/2015 (Man. Year: 2015)	Odometer:	52833 km
Colour:	Grey		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,887.57	7,751.00	3,136.57	28.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,800.00	2,510.00	1,290.00	33.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,687.57	10,261.00	4,426.57	30.14
Approved Total (Overridden) (S\$)		8,200.00		
(S\$)	14,687.57	8,200.00	6,487.57	44.17
+ GST 8.00/8.00% (S\$)	1,175.01	656.00	519.01	44.17
Nett Amount (S\$)	15,862.58	8,856.00	7,006.58	44.17

INSPECTION

Date of Assignment:	15/05/2023		
Date Inspected:	17/05/2023	Inspected At:	Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46 Singapore 408716
Estimated Period of Repair:	7.0 days		

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jun 2023)
Parts:	143	TOYOTA COROLLA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCL9888Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted / Torn	669.10 FL	*669.10 FL
2	2		*REAR BUMPER SIDE RETAINER -LH /RH	Bent	263.60 FL	*263.60 FL
3	10		*REAR BUMPER CLIPS	Necessary	55.00 FL	*55.00 FL
4	1		*REAR BUMPER REINFORCEMENT	Dented	480.20 FL	*480.20 FL
5	1		*REAR BUMPER SENSOR (TOYOTA)	Malfunction	380.50 FL	*180.10 FL
6	1		*REAR BUMPER RERFLECTORS -LH/RH	O/S Not Necessary / N/S Broken	144.40 FL	*72.20 FL
7	1		*REAR END PANEL	Dented/ Bent	808.00 FL	*808.00 FL
8	1		*REAR END PANEL TOP GARNISH	Twisted	290.40 FL	*290.40 FL
9	1		*BOOTLID	Bent / Buckled	947.10 FL	*947.10 FL
10	2		*BOOTLID HINGE -LH/RH	Not Necessary	167.80 FL	*- FL
11	10		*BOOTLID INNER TRIM CLIPS	Necessary	55.00 FL	*55.00 FL
12	1		*BOOTLID WEATHERSTRIP	Twisted	211.10 FL	*211.10 FL
13	1		*BOOTLID OUTER CHROME	Not Necessary	292.50 FL	*- FL
14	1		*BOOTLID LOGO	Necessary	69.50 FL	*69.50 FL
15	1		*BOOTLID COROLLA WORDINGS	Necessary	59.30 FL	*59.30 FL
16	2		*BOOTLID -LH/RH	Cracked	489.20 FL	*489.20 FL
17	2		*TAIL LAMP -LH/RH	Cracked	912.20 FL	*912.20 FL
18	2		*TAIL LAMP CLIPS -LH/RH	Not Necessary	11.00 FL	*- FL
19	1		*FRONT BUMPER	Torn	704.30 FL	*704.30 FL
20	1		*FRONT BUMPER SIDE RETAIONER -LH/RH	O/S Bent	205.20 FL	*102.60 FL
21	10		*FRONT BUMPER CLIPS	Necessary	55.00 FL	*55.00 FL
22	1		*FRONT BUMPER FOG LAMP -RH	Not Necessary	210.50 FL	*- FL
23	1		*FRONT BUMPER FOG LAMP COVER -RH	Torn	120.80 FL	*120.80 FL
24	1		*HEADLAMP -RH	Scratched	3,604.30 FL	*3,604.30 FL
25	1		*FRONT FEDNER -RH	Repair	1,091.50 FL	*- FL
26	1		*FRONT FENDER COWING -RH	Not Necessary	251.60 FL	*- FL
27	1		*FRONT FENDER DUAL VVT-I WORDINGS	Necessary	79.70 FL	*79.70 FL
28	10		*FRONT FENDER COWLING CLIPS -RH	Not Necessary	55.00 FL	*- FL
29	1		*SIDE MIRROR HOUSING WITH MOTOR -RH	Not Necessary	1,510.70 FL	*- FL
30	1		*SIDE MORROR LAMP -RH	Not Necessary	105.60 FL	*- FL
31	1		*SIDE MORROR OUTER COVER -RH	Not Necessary	110.70 FL	*- FL
32	1		*BOOTLID ALTIS WORDINGS	Necessary	59.30 FL	*59.30 FL
33	1		*REAR NUMBER PLATE WITH CASING	Bent	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,505.10	10,323.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,617.53	2,572.00
Total Parts (\$\$)	10,887.57	7,751.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK OUT DENTS ON BONNET ,REAR FLOOR PANEL REMOVE ,REPLACE ACCIDENT PARTS	New	1,600.00	900.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	1,800.00	1,400.00
3	TO CHECK WIRING	New	50.00	20.00
4	TO REMOVE ,REFIX GARNISH TO FACILITATE REPAIR	New	150.00	80.00
5	TO REMOVE ,REPLACE REAR SENSOR	New	80.00	50.00
6	TO TUFF-KOTE	New	120.00	60.00
Gross Labour Cost (\$\$)			3,800.00	2,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >