



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SINGAPORE PRISON SERVICE LOGISTICS BRANCH			Ref: CS/SPS23004943/Uqy3e2	
			Date: 18/05/2023	
			Code: SPS	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	PC 9452P	Veh. Inspected	GBF 4807H
	Policy No.		Coverage (\$)	0.00
	Claim No.	6000101314	Excess (\$)	0.00
	Assign From	AGNES WONG	Assign Date	15/05/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA HIACE DX (M)	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	KDH2015023817	Colour	WHITE
	Odometer	230217 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	195 R15	AUSTONE	6 mm
	L/H Front Tyre	195 R15	AUSTONE	6 mm
	R/H Rear Tyre	195 R15	AUSTONE	6 mm
	L/H Rear Tyre	195 R15	AUSTONE	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S WING MIRROR. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	08/05/2023	Inspection Date	15/05/2023
	Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	