

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT UNITED OVERSEAS INSURANCE LTD Ref: CS3/UOI23004949/Tqy3e2 146 ROBINSON ROAD Date: 18/05/2023 #02-01 UOI BUILDINGSINGAPORE 068909 Code: UOI2 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **GBF 5607L GBH 6134S** Veh. Inspected Policy No. Coverage (\$) 0.00 Claim No. M11D00192305 Excess (\$) 0.00 KATIE LEE **Assign Date** 15/05/2023 Assign From **Vehicle Particulars & Condition** 2. NISSAN NV350 Make & Model 2488 C.C HIDDEN 2016 Engine No. Year of Reg. JN1MC2E26Z0007373 SILVER Chassis No. Colour Odometer 215444 KM Steering **IN ORDER IN ORDER** NIL **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 195 R15 YOKOHAMA 6 mm YOKOHAMA L/H Front Tyre 195 R15 6 mm 195 R15 YOKOHAMA R/H Rear Tyre 6 mm YOKOHAMA L/H Rear Tyre 195 R15 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. 5. **General Information** 11/05/2023 15/05/2023 (04:00 PM) Accident Date Inspect Date / Time MASTER CAR SPRAY SERVICE Survey held at 40 TOH GUAN ROAD EAST #01-67 ENTERPRISE HUB SINGAPORE 608582 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000 5b. **Estimate Days of Repair ESTIMATED NORMAL PERIOD FOR REPAIR:** 7 Working Days

Report Ref No. CS3/UOI23004949/Tqy3e2

Inspected By

MOHAMAD TAUFIKH M.MATAI, AMSAE-A K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor