



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FU 5002E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT HEADLAMP ASSEMBLY	GRAZED	380.00	342.00
1	FRONT HEADLAMP STAY	NOT NECESSARY	95.00	-
1	FRONT METER ASSY	CRACKED	650.00	585.00
1	RHS SIDE LAMP	GRAZED	75.00	67.50
1	FRONT FAIRING	CRACKED	280.00	220.00
1	FRONT STEERING STEM UPPER	NOT NECESSARY	150.00	-
1	FRONT STEERING STEM LOWER	NOT NECESSARY	230.00	-
2	FRONT STEERING BEARING (UPPER & LOWER)	DAMAGED	140.00	126.00
1	HANDLE BAR	BENT	150.00	135.00
1	SET HANDLE BAR BALANCER	GRAZED	75.00	67.50
2	RHS MIRROR	GRAZED	95.00	85.50
1	BRAKE LEVER	BENT	90.00	81.00
1	RHS FOOT REST	GRAZED	60.00	54.00
1	RHS METAL GUARD	GRAZED	180.00	162.00
1	RHS CENTRE COVER (BLACK)	NOT NECESSARY	280.00	-
1	FUEL TANK ASSY	NOT NECESSARY	450.00	-
1	RHS RADIATOR ASSY	NOT NECESSARY	850.00	-
1	RHS EXHAUST ASSY	GRAZED	1,100.00	800.00
	LESS 10% DISCOUNT		-	-272.55
			5,330.00	2,452.95
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	IU UNIT (INCL.COST OF REFIX) (SN)	NOT NECESSARY	200.00	-
1	FRONT TYRE (SN)	NOT NECESSARY	220.00	-
1	FRONT RIM (SN)	BENT	480.00	480.00
1	REAR BOX UNIT W/BACKET (SN)	GRAZED	280.00	250.00
			1,230.00	730.00
<u>LABOUR</u>				
	TO REMOVE AND REPLACE DAMAGED PARTS AND COMPONENTS.		800.00	400.00

Report Ref No. CS1/SPF23004953/Dny3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE, REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS.		80.00	30.00
	TRANSPORT MOTORCYCLE TO WORKSHOP FOR REPAIRS.		60.00	60.00
			940.00	490.00
GRAND TOTAL			7,500.00	3,672.95
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,950.00

Report Ref No. CS1/SPF23004953/Dny3m4

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$2,850-\$3,150

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.