



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INDIA INTERNATIONAL INSURANCE PL
C/O MCLARENS SINGAPORE PTE LTD
61 ROBINSON ROAD #09-01, 61
ROBINSONSINGAPORE 068893

Ref: CS3/MCS23004980/Rqy3e2

Date: 27/07/2023

Code: III2

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GANTRY BARRIER	Veh. Inspected	SME 9636B
Policy No.	SIN.228970	Coverage (\$)	0.00
Claim No.	LPL2023D0006124	Excess (\$)	0.00
Assign From	ERNEST KHONG	Assign Date	15/05/2023

2. Vehicle Particulars & Condition

Make & Model	B.M.W. X3 XDRIVE30I	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WBATR920X0LE25888	Colour	BROWN
Odometer	61807 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/45 R20	PIRELLI	6 mm
L/H Front Tyre	245/45 R20	PIRELLI	6 mm
R/H Rear Tyre	245/45 R20	PIRELLI	6 mm
L/H Rear Tyre	245/45 R20	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/04/2023	Inspect Date / Time	18/05/2023 (04:37 PM)
Survey held at	33 LORONG PISANG EMAS		
Repairer	PERFORMANCE MOTORS LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days