



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 1315L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BONNET	BENT	891.00	891.00
1	FRONT GRILLE	CRACKED	725.00	725.00
1	FRONT GRILLE EMBLEM	NECESSARY	69.00	69.00
1	FRONT BUMPER	DEFORMED	766.00	766.00
1	FRONT BUMPER REINFORCEMENT	BENT	243.00	243.00
1	FRONT BUMPER LOWER GRILLE	CRACKED	196.00	196.00
1	FRONT BUMPER SIDE RETAINER BRKT LH	NOT NECESSARY	52.00	-
1	FRONT BUMPER SIDE RETAINER BRKT RH	NOT NECESSARY	52.00	-
1	FRONT BUMPER TOWING COVER	NOT NECESSARY	69.00	-
1	FRONT HEADLAMP LH	CRACKED	694.00	694.00
1	FRONT HEADLAMP RH	CRACKED	694.00	694.00
1	FRONT DEFLECTOR COVER LH	CRACKED	98.00	98.00
1	FRONT DEFLECTOR COVER RH	CRACKED	98.00	98.00
1	FRONT DEFLECTOR COVER TOP	CRACKED	163.00	163.00
1	FRONT A/COND CONDENSOR	NOT NECESSARY	883.00	-
1	FRONT RADIATOR	NOT NECESSARY	872.00	-
1	FRONT FENDER LH	BENT	583.00	583.00
1	FRONT SUPPORT PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT FENDER RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT DOOR LH (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-714.80	-522.00
			6,433.20	4,698.00
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT GRILLE CLIPS (SN)	NECESSARY	40.00	30.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	FRONT NUMBER PLATE (SN) }	BENT	30.00	35.00
1	FRONT NUMBER PLATE HOLDER (SN) }		20.00	-
1	FRONT RADIATOR COOLANT (SN)	NOT NECESSARY	60.00	-

Report Ref No. CS/FCI23004983/Rqy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FRONT FENDER INNER LINER CLIPS LH (SN)	NECESSARY	40.00	20.00
			240.00	115.00
	LABOUR			
	TO REMOVE, REPLACE, REFIT FRONT RADIATOR, RADIATOR FAN ASSY, AIR COND CONDENSOR, AIR COND PIPE & ETC. TO EFFECT REPAIR ON FRONT SUPPORT PANEL.		120.00	80.00
	TO REMOVE, REPLACE, REPAIR, READJUST FRONT ACCIDENT AREAS SUCH AS FRONT BONNET, FRONT BUMPER, FRONT SUPPORT PANEL, FRONT FENDER LH/RH, FRONT DOOR LH & ETC. BACK TO ORIGINAL CONDITIONS. INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL, FRONT FENDER RH AND FRONT DOOR LH.		700.00	600.00
	TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT SUPPORT PANEL, FRONT FENDER LH/RH, FRONT DOOR LH & ETC.		1,200.00	1,100.00
	TO CHECK WIRING & ELECTRICAL SYSTEM.		80.00	30.00
	TO REFILL AIR COND GAS & VACUUM.		100.00	80.00
			2,200.00	1,890.00
GRAND TOTAL			8,873.20	6,703.00

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,350.00
LESS EXCESS			-750.00
NETT LIABILITY			4,600.00

Report Ref No. CS/FCI23004983/Rqy3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.