



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNC 3985G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT R/H FENDER (N)	DENTED	952.00	952.00
1	FRONT R/H HEADLAMP (N)	CUT	3,300.00	3,300.00
1	FRONT CENTRE HEADLAMP SUPPORT RETAINER (N)	DAMAGED	312.00	312.00
1	FRONT R/H HEADLAMP LOWER BRACKET (N)	CRACKED	96.00	96.00
1	FRONT GRILLE (DIAMOND VERSION GRILLE) (N)	CRACKED	998.00	998.00
6	FRONT GRILLE CLIP (N)	NECESSARY	30.00	30.00
1	FRONT GRILLE EMBLEM (N)	NOT NECESSARY	298.00	-
1	FRONT GRILLE INNER BASE GARNISH (N)	DEFORMED	412.00	412.00
1	FRONT BUMPER (N)	DEFORMED	1,690.00	1,690.00
2	FRONT BUMPER SIDE RETAINER (N)	O/S DAMAGED	76.00	38.00
8	FRONT BUMPER CLIP (N)	NECESSARY	60.00	60.00
2	FRONT BUMPER R/H PARKING SENSOR (N)	DAMAGED (1PC ONLY)	624.00	312.00
1	FRONT BUMPER R/H SIDE GARNISH (N)	CRACKED	168.00	168.00
1	FRONT BUMPER TOP SUPPORT GARNISH (N)	NOT NECESSARY	212.00	-
1	FRONT BUMPER REINFORCEMENT BEAM (N)	BENT	726.00	726.00
1	FRONT BUMPER SPONGE (N)	CRACKED	196.00	196.00
2	FRONT R/H LOWER ARM (N)	BENT	898.00	898.00
1	FRONT R/H KNUCKLE ARM (N)	DAMAGED	856.00	856.00
1	FRONT R/H KNUCKLE HUP (N)	DAMAGED	568.00	568.00
1	FRONT R/H KNUCKLE HUP BEARING (N)	DAMAGED	312.00	312.00
1	FRONT R/H SHOCK ABSORBER (N)	BENT	986.00	986.00
	LESS 10% DISCOUNT		-	-1,291.00
			13,770.00	11,619.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT R/H 18 INCH SPORT RIM (SN)	CUT	1,860.00	1,200.00
1	FRONT R/H TYRE (235/40/R18) (SN)	NOT NECESSARY	650.00	-
			2,510.00	1,200.00
<b><u>LABOUR</u></b>				
	TO SPRAY PAINTING.		750.00	500.00

Report Ref No. CS/TP23004988/Aqp3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING.		50.00	50.00
	LABOUR CHARGE TO PANEL BEATING, WELDING, REMOVING ALL DAMAGED PARTS & REPLACING OF THE NEW PARTS ETC.		680.00	600.00
	TO COMPUTER WHEEL ALIGNMENT.		90.00	80.00
	TO REMOVE & REFIX FRONT UNDERCARRIAGE.		380.00	250.00
	TO RESET FAULT CODE & CARRY OUT DIAGNOSTIC CHECK.		180.00	120.00
	TO MEASURE, DRILL & REINSTALL THE REPLACED FRONT BUMPER POSITION & REINSTALL FRONT PARKING SENSOR, CONTROL UNTIL, CHECK & TEST FOR FUNCTIONING.		120.00	50.00
	TO APPLY UNDERCOATING ON THE REPAIRED & REPLACED PANEL FOR RUST PROTECTION.		80.00	60.00
			2,330.00	1,710.00
	<b>GRAND TOTAL</b>		<b>18,610.00</b>	<b>14,529.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>14,529.00</b>

Report Ref No. CS/TP23004988/Aqp3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.