



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDN 6688E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DENTED	1,428.50	1,428.50
2	REAR BUMPER SENSOR @\$189.40	SERVICEABLE	378.80	-
1	SET REAR BUMPER LOWER CLIP	NECESSARY	154.80	60.00
1	REAR BUMPER LOWER GUARD	GRAZED	787.20	520.00
1	REAR BUMPER LOWER INNER BEAM	SERVICEABLE	98.20	-
1	REAR BUMPER LOWER INNER SPONGE	TORN	138.50	138.50
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	799.20	-
	LESS 25% DISCOUNT		-946.30	-536.75
			2,838.90	1,610.25
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN)	NOT NECESSARY	30.00	-
			30.00	-
	<u>LABOUR</u>			
	PANEL BEATING WORK.		520.00	300.00
	CHECK WIRING.		60.00	20.00
	TO SPRAY PAINTING.		480.00	380.00
			1,060.00	700.00
	GRAND TOTAL		3,928.90	2,310.25

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			1,800.00
---	--	--	-----------------

Report Ref No. CS/INC23004989/Uvy3e2

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.