



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC23004989/Uvy3e2

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

Date: 25/05/2023

ATTN: JEFF LIN

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YQ 4139Y	Veh. Inspected	SDN 6688E
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1222624-002	Excess (\$)	0.00
Assign From	HAZALYSA	Assign Date	16/05/2023

2. Vehicle Particulars & Condition

Make & Model	LEXUS ES300H (A)	c.c	2487
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	JTHB21B1702127149	Colour	BLUE
Odometer	74644 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/45 R18	DUNLOP	6 mm
L/H Front Tyre	235/45 R18	DUNLOP	6 mm
R/H Rear Tyre	235/45 R18	DUNLOP	6 mm
L/H Rear Tyre	235/45 R18	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/05/2023	Inspect Date / Time	16/05/2023 (12:16 PM)
Survey held at	FOCUS AUTO PTE LTD NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-48 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**