

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 414D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOTLID	BENT	852.90	852.90
1	REAR END PANEL	BENT	727.70	727.70
1	REAR BUMPER REINFORCEMENT	BENT	432.50	398.70
2	REAR BOOT LAMP @\$377.60	CRACKED	755.20	755.20
1	REAR BOOT GARNISH (CHROME)	CRACKED	263.40	263.40
2	REAR LAMP @\$391.70	MTG DISTORTED	783.40	783.40
1	REAR BOOTLID LOGO	NECESSARY	56.70	56.70
1	REAR END PANEL GARNISH	DENTED	261.60	261.60
1	REAR BUMPER	BENT	423.40	423.40
10	REAR BUMPER CLIP @\$4.50	NECESSARY	45.00	45.00
10	SIDE CLIP @\$3.50	DISTORTED	35.00	35.00
1	ANTENNA ELECTRICAL	CRACKED	208.00	165.00
1	REAR BUMPER BRACKET	DISTORTED	73.70	73.70
1	COROLLA EMBLEM	NECESSARY	45.00	45.00
1	ALTIS EMBLEM	NECESSARY	55.00	55.00
	LESS 25% DISCOUNT		-1,254.63	-1,235.42
			3,763.87	3,706.28
	SPECIAL NETT ITEMS			
1	REVERSE SENSOR (SN)	SHORTED	280.00	200.00
			280.00	200.00
	<u>LABOUR</u>			
	TO RESPRAY REAR PORTION (INCLUDING REAR FENDER (L/H).		850.00	800.00
	TO RENEW ABOVE PARTS.		1,200.00	800.00
	ANTI RUST.		80.00	60.00
	TO CHECK WIRING.		50.00	20.00
			2,180.00	1,680.00
	GRAND TOTAL		6,223.87	5,586.28

Report Ref No. CS/LPC23004991/Kwy3e2



Page No.:2 of 2

Report Ref No. CS/LPC23004991/Kwy3e2

**KONG SENG CHEONG** 

**Licensed Appraiser**