

AH LIM MOTOR COMPANY

10 ANG MO KIO INDUSTRIAL PARK 2A
#01-09 AMK AUTOPOINT Singapore 568047
Tel: 6483 1244 Fax: 6483 6170 Email: ahlimmc@singnet.com.sg
GST Reg No: M9-0009639-E

SURVEYOR COPY

INSURER: India International Insurance Pte Ltd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/INDIA
Policy No:	D20MCV0000441_03	Date of Loss:	12/05/2023
Vehicle Reg. No.:	GBE6010G	Driveable?	
Driver Age/Info:	37 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CH ENGINEERING AND SERVICES PTE LTD	Contact No:	+6590629872
Driver:	HOSSAIN JAHANGIR		

Make/Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)	Vehicle Reg. Date:	26/01/2016
Vehicle Colour:	BLUE	Chassis No:	JN1SC2F24Z0858063
Engine No:	ZD30007647N		
Odometer:	0 KM		

Paint Type:
Total Loss? NO

Est. Duration of Repair
(day) 12 5 days

NOT Notified
LI Pay &
Money After Repair

Description of Accident/Loss: REFER TO THE GIA REPORT.
Remarks: PLEASE KINDLY ARRANGE SURVEY SOONEST.
Present Location: AH LIM MOTOR COMPANY (AMK)

COST OF CLAIMS

	Amount
Parts	5,011.45
Miscellaneous Items	11.00
Labour	2,170.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	7,192.45
+ GST 8.00% (\$\$)	575.40
Nett Amount (\$\$)	7,767.85

This claim is handled by: EILEEN CHUA

DETAILS

Source:

(Last Synchronised: 16 May 2023)

Model:

N/A NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)

Labour:

Repairer's (Price-denominated Standard List)

Print Code: Ah Lim Motor Company/GBE6010G/16/05/2023 11:40

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT WINDSCREEN GLASS	<i>CMH</i> 0.00	0.00	*650.00 F	✓
2	2		*FRONT WINDSCREEN MOULDING TOP LH & RH	<i>Ne</i> 0.00	0.00	*110.00 F	✓
3	2		*FRONT WINDSCREEN MOULDING SIDE LH & RH	<i>Ne</i> 0.00	0.00	*110.00 F	✓
4	1		*FRONT WINDSCREEN BOTTOM	<i>D.I</i> 0.00	0.00	*27.00 F	✓
5	1		*WIPER PANEL MOULDING		0.00	*27.00 F	✓
6	1		*UNDER MIRROR LH	<i>mi</i> 0.00	0.00	*55.00 F	✓
7	1		*SIDE MIRROR LH	<i>mi</i> 0.00	0.00	*130.00 F	✓
8	1		*SIDE MIRROR STAY LH	<i>bro</i> 0.00	0.00	*150.00 F	✓
9	1		*SIDE MIRROR STAY ROUND COVER LH	<i>mi</i> 0.00	0.00	*10.00 F	✓
10	1		*SIDE MIRROR STAY CORNER COVER LH	<i>mi</i> 0.00	0.00	*95.00 F	✓
11	1		*HEADLAMP LH	<i>Sn</i> 0.00	0.00	*285.00 F	X
12	1		*HEADLAMP LOWER COVER LH	<i>Puc</i> 0.00	0.00	*60.00 F	X
13	1		*HEADLAMP LOWER COVER CLIP	<i>now</i> 0.00	0.00	*2.50 F	X
14	1		*RADIATOR GRILLE	<i>Sn</i> 0.00	0.00	*265.00 F	X
15	1		*RADIATOR GRILLE EMBLEM	<i>Sn</i> 0.00	0.00	*55.00 F	A
16	1		*FRONT BUMPER	<i>Roller</i> 0.00	0.00	*500.00 F	✓
17	1		*FRONT PANEL CORNER LH	<i>By</i> 0.00	0.00	*240.00 F	✓
18	1		*FRONT PILLAR LH	<i>R</i> 0.00	0.00	*820.00 F	X
19	1		*STEP GARNISH LH	<i>Sn</i> 0.00	0.00	*110.00 F	X
20	1		*DOOR WINDOW GLASS LH	<i>Cur</i> 0.00	0.00	*500.00 F	✓
21	1		*DOOR WINDOW MOULDING LH	<i>Dod</i> 0.00	0.00	*82.00 F	✓
22	1		*DOOR OUTER CORNER COVER LH	<i>Red</i> 0.00	0.00	*38.00 F	✓
23	2		*DOOR HINGE LH TOP & BOTTOM	<i>R</i> 0.00	0.00	*110.00 F	X
24	1		*DOOR CHECK LH	<i>Sn</i> 0.00	0.00	*38.00 F	X
25	1		*INNER SEAL	<i>Ne</i> 0	0.00	*20.00 FS	✓
26	1		*SEALANT	<i>Ne</i> 0	0.00	*40.00 FS	✓
27	1		*ERP SEALANT	<i>Ne</i> 0	0.00	*15.00 FS	✓
28	1		*DOOR COMPANY REGISTRATION STICKER	<i>Ne</i> 0	0.00	*20.00 FS	✓

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	4,564.50
+ Margin on L,N Items 10.00% (\$\$)	446.95
Total Parts (\$\$)	5,011.45

Ah Lim Motor Company/GBE6010G/16/05/2023 11:40. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
		<u>Miscellaneous Items</u>	
1		OD/TP Case (Insurer)	11.00
Sub Total (\$\$)			11.00

Costs on Labour

Particulars	Lab.Type	Amount
Labour Items		
1 TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00 ²⁰¹
2 TO REMOVE AND REINSTALL/REPLACE FRONT WINDSCREEN.	New	120.00 ✓
3 TO REMOVE AND REINSTALL/REPLACE DASHBOARD.	New	na 350.00 X
4 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	New	na 60.00 X
5 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD FRONT PILLAR LH. TO KNOCK & REPAIR WIPER PANEL; FRONT PANEL CENTRE; DASH PANEL & INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	800.00 ⁵⁵⁰¹
6 TO SPRAY WIPER PANEL; FRONT PANEL CENTRE; FRONT PANEL CORNER LH; SIDE MIRROR CORNERCOVER LH; HEADLAMP LOWER COVER LH; FRONT DOOR LH	New	800.00 ⁵⁰⁰¹
Gross Labour Cost (\$\$)		2,170.00

Ah Lim Motor Company/GBE6010G/16/05/2023 11:40. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: