

威利摩托 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.
TEL: 6456 9830 • FAX: 6458 0128
Business Regn No: 269436/00J

*Not Authorized
L/Ring &
Resurvey After Paint
6days*

15 MAY 2023

China Taiping Insurance (Singapore) PL
105 Cecil Street
#18-00 The Octagon
Singapore 069534

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle no: PC4113B
Accident involving vehicle no: SKX7427A/PC4113B
DOA: 12/05/2023 at Mount Faber Road Lamp Post 33

Dear officer in charge
Estimate cost of repair for vehicle no: SKX7427A

To supplied:

Description	Qty	Amount
Headlamp	2	1,578.60
Front bonet	1	1,028.10
Front bonet hinge	2	119.80
Front grille w chrome	1	379.10
Front bumper	1	458.00
Front bumper retainer	2	164.60
Front bumper enforcement	1	379.20
Front fender	2	1,522.80
Front fender vvti emblem	1	38.43
Front fender cowling	2	326.80
Front support panel	1	977.60
Foglamp cover	2	225.80
Foglamp	2	496.40
Parts		7,695.23
Parts less 25%		5,771.42

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

1. Towing fees	100.00	501
2. Replace/realign new parts back to the same position		
Remove damaged parts & attachments		
Cut/weld damaged panel		
Repair dented area		
Replace/realign all parts into same position	1,200.00	7001
3. To spray paint	1,100.00	10001

	8,171.42	