

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/TMI23005017/KVP3Q2**Date:** 24/05/2023REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MC001737
Claimant Vehicle No :	SHC5149L	Insured Vehicle No :	YN1071T
Date of Loss:	12/05/2023	Nature of Claim:	TP
		Claim No:	M2302993

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5149L	Engine No:	2ZR2H35851
Make & Model:	TOYOTA PRIUS, 1.8 (A)	Chassis No:	JTDKB3FU403093151
Reg. Date:	30/11/2020 (Man. Year: 2020)	Odometer:	160492 km
Colour:	Metallic Pearl White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Sailun 4 mm
Front Right Side:	Firenza 7 mm	Rear Right Side:	Sailun 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,202.41	3,463.93	1,738.48	33.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,100.00	430.00	4,670.00	91.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,302.41	3,893.93	6,408.48	62.20
+ GST 8.00/8.00% (S\$)	824.19	311.51	512.68	62.20
Nett Amount (S\$)	11,126.60	4,205.44	6,921.16	62.20

INSPECTION

Date of Assignment:	17/05/2023		
Date Inspected:	15/05/2023	Inspected At:	Transcab Services (HQ) NO 58 DEFU LANE 1 Singapore 539498
Estimated Period of Repair:	2.0 days		

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 May 2023)
Parts:	144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC5149L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FENDER SUB-ASSY ,FRONT LH	Repair	1,236.69 FL	*- FL
2	1		*LINER ,FRONT FENDER LH	Cracked	265.55 FL	*265.55 FL
3	1		*EMBLEM ,SIDE PANEL	Not Necessary	68.88 FL	*- FL
4	1		*UNIT ASSY ,HEADLAMP ,LH	Mtg Cracked	3,325.56 FL	*3,325.56 FL
5	1		*COVER ,FRONT BUMPER	Cracked	659.40 FL	*659.40 FL
6	1		*SUPPORT ,FRONT BUMPER SIDE ,LH	Distorted	100.49 FL	*100.49 FL
7	1		*STAY SUB -ASSY ,FRONT BUMPER ,LH	Serviceable	59.85 FL	*- FL
8	1		*BRACKET ,FRONT BUMPER SIDE ,LH	Serviceable	74.97 FL	*- FL
9	1		*GRILLE ,RADIATOR ,LOWER NO.1	Serviceable	224.70 FL	*- FL
10	1		*GRILLE SUB-ASSY ,RADIATOR	Serviceable	532.88 FL	*- FL
11	1		*FRONT BUMPER ABSORBER	Cracked	100.91 FL	*100.91 FL
12	1		*SET BUMPER CLIP FRT	Necessary	65.00 FS	*60.00 FS
13	1		*SET FRONT BUMPER RETAINER CLIP	Not Necessary	85.00 FS	*- FS
14	1		*FENDER LINER CLIP	Necessary	65.00 FS	*65.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,864.88	4,576.91
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,662.47	1,112.98
Total Parts (\$\$)	5,202.41	3,463.93

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	0.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	1,600.00	200.00
4	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENT TO FACILITATE BODYWORK REPAIR	New	380.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	220.00
6	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
7	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	10.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO REMOVE AND REFIT OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (S\$)			5,100.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >