

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23005032/RNP3Q2**Date:** 30/06/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00011092200
Claimant Vehicle No :	SJA1802Y	Insured Vehicle No :	SJE7229S
Date of Loss:	04/05/2023	Nature of Claim:	TP
		Claim No:	SNM23D203204/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJA1802Y	Engine No:	17391002050882
Make & Model:	SSANGYONG TIVOLI XLV, 1.6 G 6AT 2WD ESP E4 (A)	Chassis No:	KPT36A1VSGP097496
Reg. Date:	17/02/2017 (Man. Year: 2016)	Odometer:	95306 km
Colour:	Grey		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55Z R17	Rear Tyre Size:	215/55Z R17
Front Left Side:	Roadstar 6 mm	Rear Left Side:	Roadstar 6 mm
Front Right Side:	Roadstar 6 mm	Rear Right Side:	Roadstar 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	11,265.00	4,079.41	7,185.59	63.79	
Miscellaneous Items	0.00	0.00	0.00		
Labour	6,100.00	3,840.00	2,260.00	37.05	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	17,365.00	7,919.41	9,445.59	54.39	
Approved Total (Overridden) (S\$)		6,300.00			
	(S\$)	17,365.00	6,300.00	11,065.00	63.72
+ GST 8.00/8.00% (S\$)		1,389.20	504.00	885.20	63.72
Nett Amount (S\$)	18,754.20	6,804.00	11,950.20	63.72	

INSPECTION

Date of Assignment:	16/05/2023		
Date Inspected:	17/05/2023	Inspected At:	Motorway Car Care Centre Pte Ltd No. 4 Jalan Besut Singapore 619557
Estimated Period of Repair:	8.0 days		

Adjuster: MOHD RASUL**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 Jun 2023)
Parts: M1-SUV	SSANGYONG TIVOLI XLV 1.6 G 6AT 2WD ESP E4 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJA1802Y)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	985.60 FL	*985.60 FL
2	1		*FRONT BUMPER RETAINER LH	Not Necessary	68.94 FL	*- FL
3	1		*FRONT HEADLAMP LH	Not Necessary	1,957.50 FL	*- FL
4	1		*FRONT FENDER LH	Bent	794.76 FL	*794.76 FL
5	1		*FRONT FENDER WHEEL ARCH MOULDING LH	Scratched	135.63 FL	*135.63 FL
6	1		*FRONT FENDER UNDER -DUST COVER LH	Not Necessary	135.63 FL	*- FL
7	1		*FRONT FOGLAMP GARNISH LH	Not Necessary	142.50 FL	*- FL
8	1		*FRONT DOOR LH	Bent	1,800.00 FL	*1,800.00 FL
9	1		*FRONT DOOR UPPER HINGE LH	Not Necessary	55.00 FL	*- FL
10	1		*FRONT DOOR LOWER HINGE LH	Not Necessary	55.00 FL	*- FL
11	1		*REAR DOOR LH	Repair	1,800.00 FL	*- FL
12	1		*REAR FENDER WHEEL ARCH MOULDING LH	Not Necessary	135.63 FL	*- FL
13	1		*SIDE SKIRT LH	Scratched	283.36 FL	*283.36 FL
14	1		*REAR BUMPER UPPER	Not Necessary	912.75 FL	*- FL
15	1		*FRT STABILIZER BAR ASSY LH	Not Necessary	184.20 FL	*- FL
16	1		*FRT STABILIZER BAR LINK LH	Not Necessary	46.10 FL	*- FL
17	1		*FRT SUSPENSION LWR ARM ASSY RH LH	Not Necessary	173.26 FL	*- FL
18	1		*FRT SUSPENSION DAMPER RH LH	Not Necessary	202.38 FL	*- FL
19	1		*GEAR & OBJ LINKAGE ASSY LH	Not Necessary	781.76 FL	*- FL
20	2		*RIM	Scratched (1 PCS ONLY)	1,600.00 FS	*400.00 FS
21	1		*SIDE SKIRT CLIPS	Necessary	40.00 FS	*40.00 FS
22	1		*FRONT BUMPER CLIPS	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	12,330.00	4,479.35
- List Item Discount on L Items 10.00/10.00% (\$)	1,065.00	399.94
Total Parts (\$)	11,265.00	4,079.41

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT ,CUT /WELD ,STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS	New	2,400.00	1,600.00
2	PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)	New	2,700.00	1,800.00
3	TO CARRY OUT DIAGNOSTIC TEST	New	400.00	200.00
4	TO REMOVE ,REARRAGE ELECTRICAL WIRING ,CHECK LIGHTINGS & RESET HEADLAMY FOCUSING	New	120.00	40.00
5	REMOVE FRONT UNDERCARRIAGE PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING REPLACING AFFECTED UNDERCARRIAGE PARTS AND PERFORM COMPUTERISED ALIGNMENT AND STEERING ALIGNMENT (STEERING ANGLE ZEROING)	New	480.00	200.00
Gross Labour Cost (S\$)			6,100.00	3,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >