

SIN YU SIN WORKSHOP

1 KAKI BUKIT AVENUE 6
#01-82 AUTOBAY SINGAPORE 417883

VEHICLE DETAILS

VEHICLE NO : YN5659Y 2014 JULY
VEHICLE MODEL : MITSUBISHI CANTER
CHASSIS NO : FEB21EA00196

TP ALG.

Xiao Tony

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRON BUMPER <i>Best.</i>	1	\$ 1,010.30	\$ 1,010.30
2	FRONT BUMPER BRACKET <i>Best.</i>	1	\$ 82.40	\$ 82.40
3	FRONT BUMPER SIDE PAD <i>Deformed</i>	1	\$ 330.20	\$ 330.20
4	FRONT GRILLE <i>cracked</i>	1	\$ 698.50	\$ 698.50
5	FRONT GRILLE LOGO <i>new</i>	1	\$ 85.80	\$ 85.80
6	FRONT PANEL <i>Dented.</i>	1	\$ 1,451.60	\$ 1,451.60
7	FRONT PANEL FUSO WORDING <i>new</i>	1	\$ 112.20	\$ 112.20
8	FRONT WIPER PANEL GARNISH <i>cracked.</i>	1	\$ 477.10	\$ 477.10
9	HEADLAMP <i>cracked.</i>	1	\$ 693.40	\$ 693.40
10	FRONT SIGNAL LAMP <i>3 cracked</i>	1	\$ 266.20	\$ 266.20
11	FRONT REFLECTOR SIDE <i>new</i>	1	\$ 105.70	\$ 105.70
12	FRONT WING MIRROR <i>new</i>	1	\$ 197.40	\$ 197.40
13	FRONT WING MIRROR STAY <i>Best</i>	1	\$ 352.00	\$ 352.00
14	FRONT CORNER PANEL <i>cracked.</i>	1	\$ 459.60	\$ 459.60
15	FRONT DOOR PILLAR <i>Repair</i>	1	\$ 876.90	\$ 876.90
16	FRONT STEP PANEL GARNISH <i>new</i>	1	\$ 291.50	\$ 291.50
17	FRONT WINDSCREEN <i>cracked</i>	1	\$ 1,455.80	\$ 1,455.80
18	FRONT WINDSCREEN MOULDING <i>new</i>	1	\$ 285.10	\$ 285.10
19	DASHBOARD <i>ut.</i>	1	\$ 1,655.90	\$ 1,655.90
20	WIPER MOTOR <i>new</i>	1	\$ 674.30	\$ 674.30
21	WIPER MOTOR LINKAGE <i>Best</i>	1	\$ 379.40	\$ 379.40
22	WIPER WASHER TANK <i>Deformed</i>	1	\$ 182.30	\$ 182.30
23	WIPER WAHSEER TANK MOTOR <i>new</i>	1	\$ 88.50	\$ 88.50

16083.50
7562.62

TOTAL PRICE: \$ 14,212.30
LESS 25% \$ 3,553.07
SUB TOTAL PRICE: \$ 10,144.12

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT GRILLE CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
2	FRONT WIPER PANEL GARNISH CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
3	FRONT WINDSCREEN SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
TOTAL :				\$ 120.00

120

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,600.00	<i>800.</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	<i>800.</i>	
3	WIRING CHECK	\$ 100.00	<i>30.</i>	

4	TO REMOVE FRONT WINDSCREEN	\$ 180.00	125	
5	TO VACCUM GLASS FRAGMENT	\$ 100.00	65	
6	TO APPLY TUFF COAT	\$ 150.00	65	
7	TO REMOVE DASHBOARD	\$ 350.00	220	

TOTAL: \$ 3,880.00

2080

ESTIMATE REPORT

TOTAL PARTS COST: \$ 10,264.12

TOTAL LABOUR COST: \$ 3,880.00

TOTAL REPAIR COST: \$ 14,144.12

total: 9772.62

L/S: 7.8K

07 Days

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

PART BY PART / LUMP SUM:

NO. OF DAYS:

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: