

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/ AIS 23005040/4p3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJF 58194

at Workshop m/s stytech

of _____

Insured: GAD20501

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: £ 50k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 25 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

639.
Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJF 58194 Yr Regn: 03/06/08

Type: M / Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: Harde stream c.c. 1799

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 20287 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RN 61044938

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front 6 Rear 6

R/Bal. _____ mm R/Bal. _____ mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 13/05/23 D.O.I. 18/05/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Rear w/Screen shattered

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction Rep 10k.

30/5/23 Completed 02-06-2028, LIA \$19106
1/5 @ 6100 inland w.1 ston

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

____ S + RS, ____ SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

not Allowed
18/5/23

4/5 @ 6100
6 days.

Vehicle:

SJF5819Y

Make & Model:

HONDA STREAM

Chassis No:

RN6-1044939

S/N	Parts/Labour	QTY	Unit Price	Price	Recommend	
1	Rear Bootlid			\$ 953.20	body —	903.20
2	Rear Bootlid Hinge (Left & Right)	2	\$50.80	\$ 101.60	as X	
3	Rear Bootlid Third Brake Lamp			\$ 322.80	one —	184.20
4	Rear Bootlid Glass			\$ 980.60	slotted —	860.50
5	Rear Bootlid Glass Moulding			\$ 92.60	as —	
6	Rear Bootlid Glass Sealant			\$ 60.00 SN	as 40 s/w	
7	Rear Bootlid "STREAM" Wording			\$ 48.90	as —	38.60
8	Rear Bootlid Wiper Arm			\$ 92.80	as X	
9	Rear Bootlid Wiper Blade			\$ 45.80	as X	
10	Rear Bootlid Wiper Motor			\$ 365.80	as X	
11	Rear Bootlid Handle Garnish			\$ 282.40	3rd —	
12	Rear Bootlid Handle Garnish Emblem			\$ 42.80	as/mis —	38.00
13	Rear Bootlid Handle Opener			\$ 45.60	as X	
14	Rear Bootlid Licence Plate Lamp	2	\$45.90	\$ 91.80	as X	
15	Rear Bootlid Licence Plate			\$ 40.00 SN	as s/w	
16	Rear Bootlid Lock			\$ 196.70	daye —	
17	Rear Bootlid Damper (Left & Right)	2	\$220.40	\$ 440.80	as X	
18	Rear Bootlid Inner Trim Board			\$ 428.50	as/cu —	
19	Rear Bootlid Inner Trim Board Cover			\$ 28.40	as X	
20	Rear Bootlid Inner Trim Cover (Right)			\$ 182.40	as —	
21	Rear Bootlid Inner Handle Holder			\$ 38.80	as X	
22	Taillamp (Left & Right)	2	\$459.80	\$ 919.60	as/sa 0/s/s no	388.20 17C
23	Rear Bumper			\$ 758.20	DIS —	688.20

4283.7

24	Rear Bumper Clips	1 set		\$ 30.00	SN	new / s/w	
25	Rear Bumper Retainer (Right)			\$ 48.50		sent/are /	
27	Rear Bumper Reverse Sensor	1 set		\$ 200.00	SN	born / s/w	
28	Rear Fender (Right)			\$ 758.40		20/sent /	
29	Rear Fender Glass Sealant (Right)			\$ 40.00	SN	new s/w	
30	Rear Fender Inner Trim Board (Right)			\$ 589.80		de/trim /	341.20
31	Rear End Panel			\$ 528.30		3mt /	326.50
32	Rear End Panel Garnish			\$ 268.60		trim /	
33	Whether Stripe			\$ 197.20		trim /	
34	Rear End Panel Inner Cover			\$ 299.40		11 X	
35	Rear Inner Floor Panel			\$ 658.90		R X	
36	Rear Spare Tyre Tray			\$ 253.40		11 X	
37	Rear Spare Tyre Lock Device			\$ 48.60		11 X	
38	Rear Taillamp Panel (Right)			\$ 380.80		sent/trim /	
39							
Labour							
73 replaced	1	Rear Windscreen Fixing		\$ 120.00		✓	
	2	Rear Fender Glass Fixing (Right)		\$ 80.00		60	
	3	Jack & Align Back Exhaust Pipe		\$ 120.00		11 X	
	4	Transfer Rear Boot mechanism		\$ 150.00		60	
	5	Interior Upholstery		\$ 100.00		60	
	6	Anti Rust Proofing		\$ 100.00		80	
	7	Check Wiring		\$ 100.00		20	

8	Panel Beating			\$ 1400.00	1180
10	Paint Work			\$ 1,000.00	980

STYTECH AUTO PTE. LTD.

2 Kaki Bukit Ave 2 #01-03
Kaki Bukit Autohub Singapore 417921
Tel: 6444 8125 Fax: 6445 3310
GST Reg. No.: 201601539K
Co. Reg. No.: 201601539K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-6604-9
203
P-5282-92
S.N-350
L-2560
819392
252
6145