

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 5621A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT DOOR	DENTED	1,649.00	1,568.00
1	FRONT DOOR LOWER RUBBER	NOT NECESSARY	210.10	-
1	FRONT DOOR GLASS	DAMAGED	672.35	408.00
1	FRONT DOOR MOULDING	DAMAGED	186.90	186.90
1	FRONT DOOR WEATHERSTRIP	NECESSARY	186.90	186.90
1	FRONT WINDSCREEN	NOT NECESSARY	820.80	-
1	FRONT WINDSCREEN MOULDING	CUT	1,586.00	389.00
1	FRONT CORNER GARNISH	NOT NECESSARY	296.40	-
1	SIDE VIEW MIRROR ARM	DAMAGED	368.35	368.35
1	SIDE VIEW MIRROR-SQUARE	DAMAGED	234.50	234.50
1	SIDE VIEW MIRROR-ROUND	MISSING	112.50	112.50
	LESS 25% DISCOUNT		-	-863.54
			6,323.80	2,590.61
	SPECIAL NETT ITEMS			
1	FRONT DOOR LABEL (SN)	NECESSARY	30.00	25.00
1	ERP BRACKET (SN)	NOT NECESSARY	25.00	-
1	FRONT WINDSCREEN SEALANT (SN)	NOT NECESSARY	50.00	-
			105.00	25.00
	<u>LABOUR</u>			
	TO REMOVE AND REPLACED DAMAGED PARTS INCLUDING STRAIGHTENING AND REPOSITIONING REPLACEMENT PARTS.		900.00	400.00
	SUPPLY PAINT MATERIAL AND TO RESPRAY REPLACED AND AFFECTED PANELS.		800.00	400.00
	TO REMOVE/TRANSFER DOOR FITTINGS AND ATTACHMENTS.TO CHECK FOR PROPER FUNCTIONS.		100.00	60.00
	TO REMOVE AND REPLACE FRONT WINDSCREEN RUBBER.		140.00	120.00
	TO CARRY OUT ANTI RUST TREATMENT.		80.00	30.00
			2,020.00	1,010.00
	GRAND TOTAL		8,448.80	3,625.61

Report Ref No. CS3/LPC22012849/Dny3e2-1



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,900.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CS3/LPC22012849/Dny3e2-1



Automotive Assessor / Investigator