

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
	LONPAC INSURAN	ICE BHD	Ref:	CS3/LPC22012849/Dny3e2-1
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	Date:	24/05/2023
			Code:	LPC2
1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	XB 9639D	Veh. Inspected	GBE 5621A
	Policy No.		Coverage (\$)	0.00
	Claim No.	22/22/23/VC05/026746	Excess (\$)	0.00
	Assign From	CHARMAINE KONG	Assign Date	18/05/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA 150	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	JTFAT35Y40K205554	Colour	SILVER
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15	GRENLANDER	6 mm
	L/H Front Tyre	195 R15	GRENLANDER	6 mm
	R/H Rear Tyre	155 R12 (D)	CONDOR	6/6 mm
	L/H Rear Tyre	155 R12 (D)	CONDOR	6/6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT, REAR PORTION, O/S AND N/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.			
	DAMAGES SEE DETAILS.			
5.	General Information			
	Accident Date	20/12/2022	Inspection Date	27/12/2022
	Survey held at	A T PERFORMANCE		
		160 SIN MING DRIVE #07-18/19 SIN MING AUTOCITY SINGAPORE 575722		
5a.	Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:	3 Work	ing Days