



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFJ 719L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR WINDSCREEN INNER SEAL	NOT NECESSARY	85.00	-
1	REAR TAILGATE	TO REPAIR SEE LABOUR	2,850.00	-
1	REAR TAILGATE LOGO	NECESSARY	85.00	85.00
1	REAR TAILGATE RUBBER	NOT NECESSARY	246.00	-
1	REAR TAILGATE "RENAULT" EMBLEM	NECESSARY	68.00	68.00
1	REAR TAILGATE "SCENIC" EMBLEM	NECESSARY	85.00	85.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	865.00	-
1	REAR BUMPER	DAMAGED	1,855.00	1,855.00
2	REAR BUMPER LOWER SIDE UNDERCOVERS	DAMAGED	310.00	310.00
1	REAR BUMPER LOWER DIFFUSER	DAMAGED	785.00	785.00
2	REAR BUMPER REFLECTORS	DAMAGED	236.00	236.00
1	REAR BUMPER REINFORCEMENT	DAMAGED	685.00	685.00
1	REAR BUMPER INNER GARNISH	DAMAGED	322.00	322.00
2	REAR BUMPER SIDE RETAINERS	NOT NECESSARY	130.00	-
1	REAR BUMPER LOWER MOULDING	DAMAGED	485.00	485.00
4	REAR BUMPER PDC SENSORS	DAMAGED (2PIECES ONLY)	1,260.00	630.00
1	REAR EXHAUST HEAT SHIELD	NECESSARY	185.00	185.00
	LESS 20% DISCOUNT		-2,107.40	-1,146.20
			8,429.60	4,584.80
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	80.00	30.00
			160.00	30.00
<b><u>LABOUR</u></b>				
	TO REMOVE, REFIT, REPLACED DAMAGED LAMPS AND CHECK UP REAR ELECTRICAL WIRING.		80.00	30.00
	TO REMOVE AND REFIT INNER GARNISHES, INNER TRIM TO ASSIST REPAIR.		120.00	40.00
	TO REMOVE AND REFIT REAR REVERSE SENSOR.		120.00	50.00

Report Ref No. CS3/ASM22012224/Avp3m4-1



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PROVIDE LABOUR CHARGES, WORKMASHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD ; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR TAILGATE AND REAR END PANEL.		800.00	400.00
	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT.		850.00	500.00
			1,970.00	1,020.00
<b>GRAND TOTAL</b>			<b>10,559.60</b>	<b>5,634.80</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>4,500.00</b>

Report Ref No. CS3/ASM22012224/Avp3m4-1

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.