



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNF 8933H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER UPPER	DEFORMED	912.75	912.75
1	REAR DOOR LH	TO REPAIR SEE LABOUR	1,800.00	-
1	REAR FENDER WHEEL ARCH MOULDING LH	SCRATCHED	135.63	135.63
1	REAR FENDER LH	TO REPAIR SEE LABOUR	2,868.38	-
	LESS 10% DISCOUNT		-571.68	-104.84
			5,145.08	943.54
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR BUMPER CLIPS (SN)	NECESSARY	40.00	40.00
			40.00	40.00
	<b><u>LABOUR</u></b>			
	REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT / WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS. INCLUSIVE OF THE REPAIR OF REAR DOOR LH AND REAR FENDER LH.		1,200.00	800.00
	PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER).		1,800.00	1,350.00
	TRANSFER DOOR MECHANISM.	NOT NECESSARY	200.00	-
			3,200.00	2,150.00
	<b>GRAND TOTAL</b>		<b>8,385.08</b>	<b>3,133.54</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,500.00</b>

Report Ref No. CS/SMR23005084/Rcy3m4

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.