



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: 23.30668

Date: 16th Jun 2023

Our Ref: CS3/ASM22012342/Rnp3e2-1

M/s HSBC Life (Singapore) Pte Ltd

C/o Seah Ong & Partners LLP

36 Robinson Road #12-03 City House

Singapore 068877

(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FBT 6693G

INSURED VEHICLE: SHA 8493H

ACCIDENT DATE: 06/12/2022

We thank you for your instruction on 17/05/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FBT 6693G from M/s Prudent Adjustors Services.
- b) Singapore Accident Statement of Vehicles FBT 6693G and SHA 8493H.
- c) Police Report of Vehicles FBT 6693G.
- d) Final Repair Bill of FBT 6693G from M/s M 1 Motoring.
- e) Colour damaged vehicle photographs of FBT 6693G.

Pre-Repair Inspection Date: 12/12/2022 at M/s 48 Toh Guan Road East, Repairer: M 1 Motoring.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: FBT 6693G
Make & Model	: Yamaha XMAX 300 ABS CVT
Year of Registration	: 2022
Chassis Number	: MH3SH182111015907
Engine Capacity	: 292 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.