

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG23005086/RVY3M4**Date:** 31/07/2023**REFERENCE**

Insured/Claimant:	SG SAGAWA AMERIOD PTE LTD	Policy No:	30002873207	
Date of Loss:	12/05/2023	Nature of Claim:	OD	Claim No: 314457

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XD4058C	Engine No:	E13CUN15137
Make & Model:	HINO SH1EEKA, 12.9 D (M)	Chassis No:	JHDSH1EEKXXX12040
Reg. Date:	29/01/2010 (Man. Year: 2009)	Odometer:	802583 km
Colour:	Green		
Engine Capacity:	12913 cc		
Market Value/New Car Price:	S\$28,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/80R22.5	Rear Tyre Size:	295/80R22.5 (D/D)
Front Left Side:	Rovelo 8 mm	Rear Left Side:	Rovelo 8/8 mm
Front Right Side:	Rovelo 8 mm	Rear Right Side:	Rovelo 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	47,950.72	28,640.96	19,309.76	40.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,230.00	3,400.00	830.00	19.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	52,180.72	32,040.96	20,139.76	38.60
Approved Total (Overridden) (\$\$)		20,000.00		
- Excess (\$\$)	2,000.00	2,000.00	0.00	0.00
Nett Amount (\$\$)	50,180.72	18,000.00	32,180.72	64.13

INSPECTION

Date of Assignment:	19/05/2023		
Date Inspected:	19/05/2023	Inspected At:	Lys Engineering (soon Lee Street) (HQ) 7 Soon Lee Street, #01-39 I SPACE Singapore 627608
Estimated Period of Repair:	14.0 days		

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 31 Jul 2023)	
Parts:	N/A	HINO SH1EEKA 12.9 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD4058C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN GLASS	Broken	1,200.00 F	*1,200.00 FL
2	1		*FRONT WINDSCREEN RUBBER	Necessary	480.00 F	*480.00 FL
3	3		*FRONT W/WPR BLADE ASSY	Bent	204.00 F	*204.00 FL
4	3		*FRONT W/WPR ARM ASSY	Bent	420.00 F	*420.00 FL
5	1		*FRONT TOP WIPER PANEL	Cracked	560.00 F	*560.00 FL
6	1		*SET FRONT INNER W/WPR LINK	Not Necessary	490.00 F	*- FL
7	1		*FRONT INNER W/WPR MOTOR	Not Necessary	680.00 F	*- FL
8	1		*FRONT BIG PANEL	Cracked	1,500.00 F	*1,500.00 FL
9	1		*FRONT GRILLE BIG	Cracked	950.00 F	*950.00 FL
10	1		*FRONT L & R CORNER PANEL	O/S Cracked/ N/S Not Necessary	1,300.00 F	*650.00 FL
11	1		*FRONT L & R SIGNAL LAMP	O/S Cracked/ N/S Not Necessary	440.00 F	*220.00 FL
12	1		*FRONT HINO MARK	Necessary	150.00 F	*150.00 FL
13	1		*FRONT HINO EMBLEM	Necessary	120.00 F	*120.00 FL
14	1		*FRONT 700 EMBLEM	Necessary	95.00 F	*95.00 FL
15	1		*FRONT BUMPER ASSY	Bent	1,600.00 F	*1,600.00 FL
16	2		*FRONT HEAD LAMP LEFT & RIGHT	Cracked	3,700.00 F	*3,700.00 FL
17	1		*FRONT BUMPER L & R SIDE CORNER COVER	O/S Cracked/ N/S Not Necessary	360.00 F	*180.00 FL
18	2		*FRONT BUMPER L & R CTR SIDE BLACK GARNISH COVER	Not Necessary	370.00 F	*- FL
19	1		*FRONT BUMPER CENTER BLACK GARNISH	Cracked	190.00 F	*190.00 FL
20	1		*FRONT BUMPER TOP GRILLE	Cut	380.00 F	*380.00 FL
21	1		*FRONT NO PLATE	Bent	40.00 F	*40.00 FL
22	2		*FRONT CORNER PANEL BRACKET L & R	Not Necessary	440.00 F	*- FL
23	1		*FRONT HEAD LAMP BRACKET L & R	N/S Not Necessary/ O/S Cracked	460.00 F	*230.00 FL
24	1		*FRONT BUMPER REINFORCEMENT	Bent	1,800.00 F	*1,800.00 FL
25	1		*FRONT RIGHT SIDE BUMPER COVER	Cracked	120.00 F	*120.00 FL
26	1		*FRONT RIGHT STEP GARNISH BOTTOM	Cracked	230.00 F	*230.00 FL
27	1		*FRONT RIGHT STEP ALUMINIUM BOTTOM	Cracked	160.00 F	*160.00 FL
28	1		*FRONT RIGHT STEP GARNISH REFLECTOR	Not Necessary	90.00 F	*- FL
29	2		*FRONT RIGHT STEP GARNISH BRACKET	Not Necessary	560.00 F	*- FL
30	1		*FRONT STEP GARNISH BRACKET REAR	Not Necessary	195.00 F	*- FL
31	1		*FRONT RIGHT STEP LOWER WALL	Not Necessary	210.00 F	*- FL
32	1		*FRONT RIGHT SIDE TYRE	Not Necessary	450.00 F	*- FL
33	2		*FRONT PANEL INNER LOCK	Bent	220.00 F	*220.00 FL
34	1		*SET FRONT INNER MOUNTING SHAFT	Not Necessary	1,800.00 F	*- FL
35	2		*FRONT L & R AIR BALL	Not Necessary	796.00 F	*- FL
36	1		*FRONT AIRCON CONDENSER	Bent	650.00 F	*650.00 FL
37	1		*FRONT RADIATOR ASSY	Not Necessary	6,500.00 F	*- FL
38	1		*FRONT PANEL COMPANY LOGO	Necessary	150.00 F	*150.00 FL
39	1		*FRONT PANEL INNER CYLINDER ABSORBER	Jammed	250.00 F	*250.00 FL
40	1		*FRONT INTERCOOLER ASSY	Bent	9,800.00 F	*9,800.00 FL

Report was unsubmitted during this print-out.

7/31/23, 11:34 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*FRONT BUMPER REINFORCEMENT INNER BRACKET	Bent	940.00 F	*940.00 FL
42	1		*AIR CON BLOWER UNIT	Cracked	1,325.64 F	*1,325.64 FL
43	1		*AIR CON EVAPORATOR UNIT	Cracked	998.23 F	*998.23 FL
44	1		*AIR CON COOLING COIL	Not Necessary	1,266.43 F	*- FL
45	1		*AIR CON FILTER	Necessary	80.00 F	*80.00 FL
46	1		*FRONT WIPER WATER TANK	Not Necessary	480.00 F	*- FL
47	1		*FRONT INSTRUMENT PANEL CLASH PAD	Bent	950.42 F	*950.42 FL
48	1		*FRONT CLUSTER METER PAD	Cracked	1,100.00 F	*1,100.00 FL
49	1		*FRONT RIGHT SIDE UPPER STEP PANEL	Not Necessary	520.00 F	*- FL
50	2		*AIR CON PIPE	Bent	180.00 F	*180.00 FL
F=Franchise part. L=ListItemDisc.						
					Sub Total (S\$)	47,950.72 31,823.29
					- List Item Discount on L Items 0.00/10.00% (S\$)	0.00 3,182.33
					Total Parts (S\$)	47,950.72 28,640.96
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REFILL AIRCON GAS & TEST FOR LEAKAGES	New	80.00	0.00
2	TOWING VEHICLE SERVICE CHARGE	New	150.00	0.00
3	TO SPRAY PAINTING FRONT BODY & RIGHT BODY & INNER BODY	New	1,200.00	900.00
4	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN,KNOCK OUT & TO DISMANTLE THE FRONT WINDSCREEN GALSS,FRONT INNER MOUNTING SHAFT & AIR BALL 2 PCS	New	2,800.00	2,500.00
Gross Labour Cost (S\$)			4,230.00	3,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >