



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI23005093/Avy3e2 Date: 10/07/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SBS 6411J	Veh. Inspected	SLQ 6869P
Policy No.		Coverage (\$)	0.00
Claim No.	D23001750MFBP	Excess (\$)	0.00
Assign From	HARMINDER	Assign Date	18/05/2023
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA CHR	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	ZYX102039928	Colour	BROWN
Odometer	114577 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/55 R17	GITI	6 mm
L/H Front Tyre	225/55 R17	GITI	6 mm
R/H Rear Tyre	225/55 R17	GITI	6 mm
L/H Rear Tyre	225/55 R17	GITI	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	17/05/2023	Inspection Date	19/05/2023
Survey held at	AUTOMOBILE HUB ENTERPRISE 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	