

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/AIS23005095/KVP3Q2**Date:** 24/05/2023REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SJS8560D**Insured Vehicle No :** GBG8563D

Date of Loss: 10/05/2023

Nature of Claim: TP

Claim No: 2023 32008255FR

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJS8560D**

Make &amp; Model: MERCEDES-BENZ B180, 1.5 (A)

Engine No: 26694030672614

Reg. Date: 11/09/2009 (Man. Year: 2009)

Chassis No: WDD2452322J508593

Colour: White

Odometer: 131134 km

Engine Capacity: 1699 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Pirelli 8 mm

Rear Left Side: Pirelli 8 mm

Front Right Side: Pirelli 8 mm

Rear Right Side: Pirelli 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,257.75	2,451.65	1,806.10	42.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,530.00	825.00	705.00	46.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,787.75</b>	<b>3,276.65</b>	<b>2,511.10</b>	<b>43.39</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,600.00</b>		
<b>Nett Amount (S\$)</b>	<b>5,787.75</b>	<b>2,600.00</b>	<b>3,187.75</b>	<b>55.08</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

INSPECTION

Date of Assignment: 18/05/2023

Date Inspected: 18/05/2023 Inspected At:

Authorize Workshop Pte Ltd (HQ)

160 Sin Ming Drive, #03-19 Sin Ming Autocity

Singapore 575722

Estimated Period of Repair: 3.0 days

**Adjuster:** KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 May 2023)
Parts:	144	MERCEDES-BENZ B180 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJS8560D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Cracked	1,178.80 FL	*1,178.80 FL
2	1		*REAR BUMPER SCUFF PLATE	Bent	180.40 FL	*180.40 FL
3	2		*REAR BUMPER SIDE MOULDING L/R	Necessary	292.00 FL	*292.00 FL
4	2		*REAR BUMPER REFLECTOR L/R (NPA)	Serviceable	0.00 FL	*- FL
5	1		*REAR BUMPER LOWER GARNISH	Dented / Cut	250.70 FL	*250.70 FL
6	2		*REAR BUMPER SIDE HOLDER L/R (NPA)	Serviceable	0.00 FL	*- FL
7	2		*REAR BUMPER ADHESIVE FOIL L/R (NPA)	Serviceable	0.00 FL	*- FL
8	1		*REAR LAMP RH	Serviceable	525.00 FL	*- FL
9	1		*REAR FENDER INNER LINER RH (NPA)	Serviceable	0.00 FL	*- FL
10	1		*REAR END PANEL	Repair	1,204.00 FL	*- FL
11	4		*PDC SENSOR	Shorted (2 PCS ONLY)	500.00 FS	*250.00 FS
12	1		*REAR BUMPER REINFORCEMENT	Bent	483.27 FL	*483.27 FL
13	1		*SET REAR BUMPER CLIPS	Necessary	55.00 FS	*55.00 FS
					Sub Total (\$\$)	4,669.17 2,690.17
					- List Item Discount on L Items 10.00/10.00% (\$\$)	411.42 238.52
					Total Parts (\$\$)	4,257.75 2,451.65

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REARRANGE ELECTRICAL WIRINGS ,CHECK LIGHTINGS	New	80.00	15.00
2	TO REMOVE ,REPAIR & REPLACE DAMAGED BODYPARTS ,REALIGN BODYWORK AND WHERE CONSISTENT TO THE ACCIDENT	New	600.00	350.00
3	PUTTY AND RESPRAY PAINTING ON AFFECTED PORTIONS	New	600.00	400.00
4	TO REMOVE & RENEW REVERSE SENSOR	New	150.00	60.00
5	RUST PROOFING ON AFFECTED PORTIONS	New	100.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,530.00</b>	<b>825.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >