

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





| AUTOMOBILE INSPECTION REPORT                        |  |                                     |         |                       |                    |  |
|---|--|-------------------------------------|---------|-----------------------|--------------------|--|
| INCOME INSURANCE LTD                                |  |                                     | Ref:    | NS/INC23005099/Svp3m4 |                    |  |
| 75 BRAS BASAH ROAD<br>INCOME CENTRESINGAPORE 189557 |  |                                     | Date:   | 26-06-2023<br>INC4    |                    |  |
| 1. Policy Particulars :- THIRD PARTY CLAIM          |  |                                     |         |                       |                    |  |
|   | Insured Veh.   | FBP 1222L                           | Veh. Ir | nspected              | SH 9418C           |  |
|   | Policy No.   |                                     | Covera  | age (\$)              | 0.00               |  |
|   | Claim No.  | MT/1220894-002                      | Exces   | s (\$)                | 0.00               |  |
|   | Assign From  |                                     | Assign  | n Date                | 27/04/2023         |  |
| 2. Vehicle Particulars & Condition                  |  |                                     |         |                       |                    |  |
|   | Make & Model   | HYUNDAI I40                         | c.c     |                       | 1685               |  |
|   | Engine No.   | HIDDEN                              | Year o  | f Reg.                | 2017               |  |
|   | Chassis No.  | KMHLB41UMHU098197                   | Coloui  | ſ                     | BLUE               |  |
|   | Odometer   | 711493                              | Steerii | ng                    | IN ORDER           |  |
|   | Brakes   | IN ORDER                            | Modifi  | cation                | STANDARD ALLOY RIM |  |
|   | General  | GOOD                                |         |                       |                    |  |
| 3. Conditions of Tyres                              |  |                                     |         |                       |                    |  |
|   |  | Size                                | Make    |                       | Balance            |  |
|   | R/H Front Tyre   | 205/60R16                           | WEST    | LAKE                  | 5 mm               |  |
|   | L/H Front Tyre   | 205/60R16                           | WEST    | LAKE                  | 5 mm               |  |
|   | R/H Rear Tyre  | 205/60R16                           | WEST    | LAKE                  | 5 mm               |  |
|   | L/H Rear Tyre  | 205/60R16                           | WEST    | LAKE                  | 5 mm               |  |
| 4.  | 4. Description of Damages  |                                     |         |                       |                    |  |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.  |                                     |         |                       |                    |  |
|   | DAMAGES SEE DETAILS.   |                                     |         |                       |                    |  |
| 5.  | General Information  |                                     |         |                       |                    |  |
|   | Accident Date  | 26/04/2023                          | Inspec  | tion Date             | 27/04/2023         |  |
|   | Survey held at COMFORTDELGRO ENGINEERING PTE LTD   |                                     |         |                       |                    |  |
|   |  | 59 LOYANG DRIVE<br>SINGAPORE 508969 |         |                       |                    |  |
| 5a.   |  |                                     |         |                       |                    |  |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                     |         |                       |                    |  |
| 5b.   | Estimate Days of Repair  |                                     |         |                       |                    |  |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days   |                                     |         |                       |                    |  |