



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)

Ref: CS3/SPF23005104/Kny3e2

ACCIDENT CLAIMS SECTION (SPORE POLICE
FORCE) POLICE LOGISTICS BASE (PLB) 1
HEMMANT ROAD SINGAPORE 438675

Date: 15/06/2023

ATTN: LUI LAI KUEN

Code: SPF

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	QX 2061H	Veh. Inspected	SGU 1981T
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2023/032	Excess (\$)	0.00
Assign From	LUI LAI KUEN	Assign Date	18/05/2023

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ C180 (A)	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WDD2053402F333288	Colour	METALLIC GREY
Odometer	123889 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/30Z R20	MICHELIN	8 mm
L/H Front Tyre	245/30Z R20	MICHELIN	8 mm
R/H Rear Tyre	245/30Z R20	MICHELIN	8 mm
L/H Rear Tyre	245/30Z R20	MICHELIN	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/04/2023	Inspect Date / Time	29/05/2023 (10:16 AM)
Survey held at	KEE YONG AUTOMOBILE SERVICE 160 SIN MING DRIVE, #03-09, SIN MING AUTOCITY, SINGAPORE 575722		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------