

### **GARAGE 13 PTE LTD**

8 KAKI BUKIT AVE 4 #02-54/55 PREMIER@KB SINGAPORE 415875

UEN GST REG NO: 202005684D

Date : 16/5/2023 Proforma Ref No : G13/23091

To : Kee Kay Leong

Vehicle No : EL7711M Accident Date : 24/6/2022

PROFORMA INVOICE		
Description		Amount
Repair Cost	\$	6,300.00
Sub-Tota GST 8%		6,300.00 504.00
TOTAL	\$	6,804.00

Payment by cheque should be crossed and made payable to 'Garage 13 Pte Ltd'

Issued By:

**Authorised Signature** 

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800 Hotline: **6385 1171** 

Our reference:

22 - 170881

Date:

12/07/2022

**INVOICE NO. 170881** 

Kee Kay Leong c/o Garage 13 Pte Ltd 8 Kaki Bukit Ave 4 #03-46 Premier@KB Singapore 415875

Registration No.

**EL7711M** 

We enclose our fee note for your kind attention, which remains payable irrespective of the outcome of this case.

S/No.	Description of Services Provided	Qty	Amount
1	Being vehicle damage assessment report, inspection, photographs, transport and miscellaneous.	1	\$ 652.00
		Total amount	\$ 652.00

Please kindly cross all cheques made payable to "Impact Analysis Consulting Pte Ltd ".

We thank you in anticipation for your prompt payment.

~

L. L. Tan (Ms)

Principal Consultant

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800

Hotline: 6385 1171

Our reference:

22 - 170881

Date:

12/07/2022

c/o Garage 13 Pte Ltd 8 Kaki Bukit Ave 4 #03-46 Premier@KB Singapore 415875

Dear Sirs

RE:

Road Traffic Accident on 24-06-2022

Kee Kay Leong

In accordance with your instructions received in this office on

28-06-2022

, we made arrangements to

examine the vehicle on

28-06-2022

at above-mentioned address. The following data was

recorded:

#### Vehicle details

Make	Nissan	Registration	EL7711M
Model	QASHQAI 2.0 CVT ABS D/AIRBAG 2WD 5DR S/R	Chassis	SJNFBAJ11U1778271
Colour	Red	Gearbox	Auto
Odometer	176499km	Paintwork	Good
Steering	In order	Brakes	In order
Condition	Good		

#### Tyre Depths

Front left	235/50ZR19	85% Rotalla
Front right	235/50ZR19	85% Rotalla
Rear left	235/50ZR19	85% Rotalla
Rear right	235/50ZR19	85% Rotalla

Status	REPAIRABLE		
Magnitude	Medium		
Legal status	Unroadworthy		

#### Impact Direction & Area of Damage:



Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of \$6,300.00 7 working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800 Hotline: **6385 1171** 

Our reference:

22 - 170881

Date

12/07/2022

Page

2

# Section A: Damaged Parts Assessment

Section A: Da	amaged P	arts Assessme	nt		
Part's Description	Qty	Condition As inspected	Repairer's Estimate	Our Adjustment	
List Items :					
Front bumper	1	deformed	717.00	717.00 68	32
Front bumper side retainer rh	1	cracked	38.50	38.50	
Front foglamp finisher rh	1	refix	102.00	0.00 XI	NN
Front foglamp rh	1	refix	298.66	0.00 XN	IN
Front fender rh	1	distorted	588.00	588.00	
Front fender outer arch garnish rh	1	deformed	296.00	296.00	
Front fender inner shield rh	1	torn	125.00	125.00	
Bonnet	1	repair.respray	984.50	0.00 X	R
Headlamp rh	1	cracked	1225.00	1225.00	
Front radiator grille c/w chrome moulding	1	holder broken	396.00	396.00	
Front lower arm rh	1	bent	271.00	271.00 XN	IN
Front knuckle arm rh	1	bent	481.94	481.94 XI	NN
Front wheel hub and bearing rh	1	necessary	247.33	247.33 XN	N 1
Front linkage rh	1	bent	98.00	98.00 XN	IN
Front shock absorber rh	1	bent	493.85	493.85 XN	IN
	Sub- Total	cost	6362.78	4977.62	3350.50
Percentage	e discount :	10%	636.28	497.76	3015.45
Sub	-Total costs	for parts	5726.50	4479.86	
Special Nett Items:					
Front bumper clips	set	necessary	50.00	50.00 30	
Front radiator grille clip	set	necessary	15.00	15.00	
Front tyre rh	1	refix	290.00	0.00 XI	IN
Front rim rh	1	bent	980.00	980.00 65	0
Front fender inner shield clip rh	set	necessary	30.00	30.00 20	1
Sub	-Total costs	for parts	1365.00	1075.00	715

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800 Hotline: **6385 1171** 

Our reference:

22 - 170881

Date

12/07/2022

**Parts Repair** 

Front door rh - slightly dented

1 repair.respray 0.00 0.00 xR

Sub-Total costs 0.00 0.00

Total costs for parts 7091.50 5554.86

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800 Hotline: **6385 1171** 

Our reference:

22 - 170881

Date

12/07/2022

Page

3

### **Section B: Labour Cost Calculation**

	Hourly rate	Manhr. Req.	Total		1
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.	\$ 45.00	20	\$	900.00	5
Putty & Spray painting to adjacent panels. Job allowance. Paint / material.	Sub-contract work.		\$	900.00	80
Apply rust proofing on the adjacent panels.	Sub-contract work.		\$	50.00	3
Specialist charges - Wheel alignment	-	-	\$	60.00	
Remove and replace front undercarriage work rh		5	\$	225.00	x
ecialist charges - Check/Diagnostic and reprogramming		-	\$	200.00	15
Wiring / bulb checking (inclusive of re-focus / re-adjust on angle of light intensity.)	\$ 45.00	0.8	\$	36.00	3
	Total la	bour cost	\$	2,371.00	1:

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and in-house@ IA Research Guidelines respectively.

5300.45 l/s\$4250 5 days #

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800 Hotline: **6385 1171** 

Type text here

Our reference:

22 - 170881

Date

12/07/2022

## **Section C: Summary Table of Total Repair Cost**

Description		Cost	
Damag	ed Parts		
Asses	sment	\$5,554.86	
(See se	ction A)		
Labour Cost	Calculation	\$2,371.00	
(See section B)		\$2,371.00	
Total cost		\$7,925.86	
Lump Sum		V.	
Further discount 20%		\$1,585.17	
Total Repair Cost		\$6,300.00	

We would recommend a sum of	\$6,300.00	and	7	working days for repair.
No further items will be approved with	thout our expressed	d written agreen	nent. Any sigr	nificant additional
items will be subject to a supplement	tary report.			
				Т
Mechanical Engineer, Accident Expert W	itness, Licensed Appr	aiser (Automobile	)	
B.Eng. (Hons, NUS)	5.0			
Diploma.Mechanical Engineering				
NTC-2 Automovite Technology				
Sr.MIES, Institution of Engineers, Singe	apore (#20100091)			
MATAI, Maryland Association of Traff	ic Accident Investigo	itors		
IAARS, International Association of Ac	ccident Reconstruction	on Specialists		
PMC of Singapore Business Advisors & Co	onsultants Council			
ACTA certified Trainer, Singapore				

Enterprise Singapore - Recognised Certification for Management Consultants IMI Professional Certificate In Vehicle Accident Damage Assessment (UK)

































































































































































































































































