



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBQ 3109M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
2	HANDLE BAR @\$707.00	NOT NECESSARY	1,414.00	-
2	MIRROR @\$279.00	NOT NECESSARY	558.00	-
1	WINDSHIELD	CUT / BENT	334.00	334.00
2	HEAD UPPER TRIM @\$667.00	CUT / GRAZED	1,334.00	1,334.00
1	LOW BEAM HEADLAMP (LH)	BROKEN	986.00	986.00
1	HIGH BEAM HEADLAMP (RH)	NOT NECESSARY	916.00	-
1	AIR-INLET DUCT	NOT NECESSARY	326.00	-
1	FRONT FENDER	NOT NECESSARY	567.00	-
2	PLAQUE HOLDER @\$206.00	BENT	412.00	412.00
2	FRONT SIDE FAIRING @\$1992.00	CUT	3,984.00	3,984.00
2	FAIRING BADGE @\$148.00	NECESSARY	296.00	296.00
2	FRONT LED TURN INDICATOR @\$172.00	BROKEN / CUT	344.00	344.00
2	ENGINE SPOILER @\$953.00	CUT	1,906.00	1,906.00
1	FUEL TANK CENTER COVER	CUT	513.00	513.00
2	FUEL TANK SIDE COVER @\$206.00	NOT NECESSARY	412.00	-
1	TIMING COVER RH	BROKEN	360.00	360.00
1	BRAKE PEDAL	NOT NECESSARY	408.00	-
1	TAIL UPPER COVER	CUT	1,127.00	1,127.00
1	TAIL LOWER COVER	NOT NECESSARY	577.00	-
2	REAR LED TURN INDICATOR @\$141.00	N/S BROKEN	282.00	141.00
	LESS 10% DISCOUNT		-1,705.60	-1,173.70
			15,350.40	10,563.30
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN)	NECESSARY	20.00	15.00
1	BODY FRAME SLIDER (SN)	CUT / BENT	200.00	180.00
1	EXHAUST MUFFLER (SN)	CUT / DENTED	2,425.00	1,500.00
			2,645.00	1,695.00
<u>LABOUR</u>				
	TOWING FEE.		80.00	60.00

Report Ref No. CS3/HSB23001146/Rvp3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RENEW DAMAGED PARTS & REPAIR AFFECTED AREAS.		500.00	300.00
			580.00	360.00
	GRAND TOTAL		18,575.40	12,618.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				10,100.00

Report Ref No. CS3/HSB23001146/Rvp3e2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.