

ASS. REC. BY:

REF:

AIG/ 2300 5122/Kp

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SNJ 7991A Yr Regn: 02, 23

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NIS Perena E-Power CC 1198Colour: M. Orange A/C: Insured / Std / NI / NASp. Reading: 16764 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JNIEBA 0278 0001820Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 7 mmL/Bal. 6 mm L/Bal. 7 mmD.O.A. 17/5/23 D.O.I. 19/5/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

5/6 3750/ Cah

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____
S + RS. \$ _____

Paints

Others

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Date: 19/05/2023

Vehicle No: SNJ7991A

Model: NISSAN SERENA 1.2L HIGHWAY STAR

Chassis: JN1EBAC27Z0001620-2023

Reg.Year: 2023

*Not Notified
11 May @ 3750h*

Third Party Insurer: AIG

Third Party Veh No: SJZ906G

Date of Accident: 17/05/2023

Estimator: TING AN

Surveyor:

Resurvey After Pains 4 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE <i>1880.40</i>	1		<i>By</i> \$2,090.00
2	REAR TAILGATE "HIGHWAY STAR" EMBLEM	1		<i>re</i> \$88.00
3	REAR TAILGATE "E-POWER" EMBLEM	1		<i>re</i> \$110.00
4	REAR TAILGATE LOCK	1		<i>re</i> \$288.00
5	REAR BUMPER <i>1527.</i>	1		<i>Br</i> \$1,555.00
6	REAR BUMPER PARKING SENSOR <i>250.40</i>	1		<i>short</i> \$332.00
SUB TOTAL				\$4,463.00
LESS 10%				-\$446.30
PARTS TOTAL				\$4,016.70

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE INNER TRIM BOARD CLIPS	1		<i>re</i> \$50.00
2	REAR BUMPER CLIPS	1		<i>re</i> \$50.00
S/N TOTAL				\$100.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

400
\$500.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER & ETC.

440
\$500.00

LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN MOULDING, REAR WINDSCREEN SEALANT & ETC.

120
\$150.00

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.

60
\$120.00

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

80
\$120.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 19/05/2023
Vehicle No: SNJ7991A
Model: NISSAN SERENA 1.2L HIGHWAY STAR
Chassis: JN1EBAC27Z0001620-2023
Reg.Year: 2023

Third Party Insurer: AIG
Third Party Veh No: SJZ906G
Date of Accident: 17/05/2023
Estimator: TING AN
Surveyor:

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$120.00 301

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

nn \$100.00 X

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$80.00 201

LABOUR TOTAL \$1,690.00

TING AN

TOTAL \$5,806.70

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143

Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500

Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 569047

Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

