

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ERGO Insurance Pte. Ltd.
8 Temasek Boulevard, #04-01 Suntec Tower Three
Singapore 038988

Our File No: CS/EGI23005123/TVY3M4**Date:** 28/06/2023**REFERENCE**

Insured/Claimant: CHENG FONG ENTERPRISES (S) PTE LTD Policy No: DMPG23003128
Date of Loss: 17/05/2023 Nature of Claim: OD Claim No: CDMPG23001215

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKU3339M**
Make & Model: TOYOTA LEXUS, 2.0 RX300 5DR SUV (AT) (4WD) LUXURY (A) Engine No: 8ARW996745
Reg. Date: 29/03/2019 (Man. Year: 2018) Chassis No: JTJBAMCA302067856
Colour: White Odometer: 84611 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$188,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/55R20 Rear Tyre Size: 235/55R20
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,641.00	23,044.00	3,597.00	13.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,790.00	1,280.00	510.00	28.49
Paintwork Labour	1,300.00	1,200.00	100.00	7.69
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,731.00	25,524.00	4,207.00	14.15
- Excess (S\$)	0.00	700.00	-700.00	
(S\$)	29,731.00	24,824.00	4,907.00	16.50
+ GST 8.00/8.00% (S\$)	2,378.48	1,985.92	392.56	16.50
Nett Amount (S\$)	32,109.48	26,809.92	5,299.56	16.50

INSPECTION

Date of Assignment: 19/05/2023 Present Location: Vin's Motor Pte Ltd (Sin Ming)
VIN'S MOTOR PTE LTD
Date Inspected: 19/05/2023 Inspected At: 160 SIN MING DRIVE
#03-03 SIN MING AUTO CITY
SINGAPORE 575722
Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jun 2023)
Parts:	143	TOYOTA LEXUS 2.0 RX300 5DR SUV (AT) (4WD) LUXURY (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKU3339M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET (order) (WCP)	Bent	1,500.00 F	*1,500.00 F
2	1		*BONNET RH HINGE (WCP)	Bent	50.00 F	*50.00 F
3	1		*BONNET LH HINGE (WCP)	Bent	50.00 F	*50.00 F
4	1		*BONNET RH ABSORBER (order) (WCP)	Not Necessary	170.00 F	*- F
5	1		*BONNET LH ABSORBER (order) (WCP)	Not Necessary	170.00 F	*- F
6	1		*BONNET RUBBER (WCP)	Cut	60.00 F	*60.00 F
7	1		*BONNET INSULATOR (WCP)	Not Necessary	260.00 F	*- F
8	1		*BONNET LOCK (WCP)	Bent	80.00 F	*80.00 F
9	1		*RH HEADLAMP (order) (WCP)	Cracked	3,200.00 F	*3,200.00 F
10	1		*LH HEADLAMP (order) (WCP)	Cracked	3,200.00 F	*3,200.00 F
11	1		*FRONT TOP GRILLE (WCP)	Deformed	650.00 F	*650.00 F
12	1		*FRONT LOWER GRILLE (WCP)	Cracked	160.00 F	*160.00 F
13	1		*FRONT TOP GRILLE OUTER CHROME MOULDING (WCP)	Cracked	280.00 F	*280.00 F
14	1		*FRONT LOWER GRILLE CHROME MOULDING (order) (WCP)	Cracked	440.00 F	*440.00 F
15	1		*FRONT TOP GRILLE RUBBER (WCP)	Twisted	30.00 F	*30.00 F
16	1		*FRONT GRILLE EMBLEM (order) (WCP)	Cut	220.00 F	*220.00 F
17	1		*FRONT GRILLE RH COVER (WCP)	Missing	40.00 F	*40.00 F
18	1		*FRONT GRILLE LH COVER (WCP)	Missing	40.00 F	*40.00 F
19	1		*FRONT CAMERA (order) (WCP)	Cut	1,100.00 F	*1,100.00 F
20	1		*FRONT BUMPER (order) (WCP)	Deformed	450.00 F	*450.00 F
21	1		*FRONT BUMPER NO.PLATE GARNISH (WCP)	Deformed	80.00 F	*80.00 F
22	1		*FRONT BUMPER LH NOZZIE GUN (WCP)	Not Necessary	270.00 F	*- F
23	1		*FRONT BUMPER RH NOZZIE GUN COVER (WCP)	Not Necessary	20.00 F	*- F
24	1		*FRONT BUMPER LH NOZZIE GUN COVER (WCP)	Not Necessary	20.00 F	*- F
25	1		*FRONT BUMPER RH FOG LAMP (WCP)	Not Necessary	210.00 F	*- F
26	1		*FRONT BUMPER LH FOG LAMP (WCP)	Not Necessary	210.00 F	*- F
27	1		*FRONT BUMPER RH FOG LAMP COVER (WCP)	Not Necessary	50.00 F	*- F
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*FRONT BUMPER LH FOG LAMP COVER (WCP)	Not Necessary	50.00 F	*- F
29	1		*FRONT BUMPER RH FOG LAMP CHROME TRIM (WCP)	Not Necessary	70.00 F	*- F
30	1		*FRONT BUMPER LH FOG LAMP CHROME TRIM (WCP)	Not Necessary	70.00 F	*- F
31	1		*FRONT BUMPER LH SIDE COVER (WCP)	Not Necessary	70.00 F	*- F
32	1		*FRONT BUMPER RH SIDE COVER (WCP)	Not Necessary	70.00 F	*- F
33	1		*FRONT BUMPER RH SIDE PAD (WCP)	Not Necessary	80.00 F	*- F
34	1		*FRONT BUMPER LH SIDE PAD (WCP)	Deformed	80.00 F	*80.00 F
35	1		*FRONT BUMPER RH SIDE RETAINER (WCP)	Not Necessary	70.00 F	*- F
36	1		*FRONT BUMPER LH SIDE RETAINER (WCP)	Deformed	70.00 F	*70.00 F
37	1		*FRONT BUMPER SPONGE (WCP)	Cracked	60.00 F	*60.00 F
38	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	350.00 F	*350.00 F
39	1		*FRONT REINFORCEMENT RH BRACKET (order) (WCP)	Not Necessary	80.00 F	*- F
40	1		*FRONT REINFORCEMENT LH BRACKET (order) (WCP)	Not Necessary	80.00 F	*- F
41	1		*FRONT BUMPER UNDER COVER (WCP)	Not Necessary	110.00 F	*- F
42	10		*FRONT BUMPER CLIPS (WCP)	Necessary	20.00 F	*20.00 F
43	1		*FRONT SUPPORT PANEL (order) (WCP)	Bent	1,300.00 F	*1,300.00 F
44	1		*FRONT SUPPORT PANEL TOP COVER (WCP)	Deformed	230.00 F	*230.00 F
45	10		*FRONT SUPPORT PANEL TOP COVER CLIPS (WCP)	Necessary	20.00 F	*20.00 F
46	1		*BRACE PANEL (WCP)	Bent	160.00 F	*160.00 F
47	1		*AIRCON CONDENSER (order) (WCP)	Bent	1,400.00 F	*1,400.00 F
48	1		*RADIATOR (order) (WCP)	Bent	1,800.00 F	*1,800.00 F
49	1		*RADIATOR RH SIDE GUIDE (WCP)	Deformed	70.00 F	*70.00 F
50	1		*RADIATOR LH SIDE GUIDE (WCP)	Deformed	70.00 F	*70.00 F
51	1		*INTER COOLER (order) (WCP)	Bent	40.00 F	*450.00 F
52	1		*BATTERY BRACKET (WCP)	Not Necessary	60.00 F	*- F
53	1		*BATTERY TRAY (WCP)	Not Necessary	60.00 F	*- F
54	1		*AIR CLEANER BOX ASSY (WCP)	Not Necessary	800.00 F	*- F
55	1		*SMOG SENSOR (ECS) (WCP)	Cracked	210.00 F	*210.00 F
56	1		*FRONT RH FENDER (WCP)	Repair	520.00 F	*- F
57	1		*FRONT LH FENDER (WCP)	Bent	520.00 F	*520.00 F
58	1		*FRONT RH FENDER TOP COVER (WCP)	Not Necessary	110.00 F	*- F
59	1		*FRONT LH FENDER TOP COVER (WCP)	Deformed	110.00 F	*110.00 F
60	1		*FRONT LH WHEEL ARCH GARNISH (WCP)	Deformed	130.00 F	*130.00 F
61	1		*FRONT RH SEAT BELT (WCP)	Activated	900.00 F	*900.00 F
62	1		*FRONT LH SEAT BELT (WCP)	Activated	900.00 F	*900.00 F
63	2		*AIRBAG SENSOR (WCP)	Activated	360.00 F	*360.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
64	1		*FRONT NO.PLATE	Bent	40.00 FS	*40.00 FS
65	1		*COOLANT	Necessary	80.00 FS	*80.00 FS
F=Franchise part. S=SpcNett.						
Sub Total (\$)					24,230.00	20,960.00
+ Margin on L,N Items 10.00/10.00% (\$)					2,411.00	2,084.00
Total Parts (\$)					26,641.00	23,044.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TO SPRAY PAINTING	New	1,300.00	1,200.00
<u>Labour Items</u>				
2	TO REFILL AIRCON GAS	New	150.00	100.00
3	TO REFILL AIRCON GAS TO RESET HEADLAMP SYSTEM INSTEAD OF REFILL AIRCON GAS	New	280.00	180.00
4	TO RESET AIRBAG SYSTEM	New	380.00	200.00
5	TO REPAIR DAMAGES	New	980.00	800.00
Gross Labour Cost (\$\$)			3,090.00	2,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >