

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
	LONPAC INSURAI	NCE BHD	Ref:	CS3/LPC23005126/Kny3m4
	300 BEACH ROAD #17-04/07 THE CC) NCOURSESINGAPORE 199555	Date:	26/05/2023
			Code	: LPC2
1.	Policy Particulars :- (THIRD PARTY CLAIM)			
	Insured Veh.	GBC 4023T	Veh. Inspected	SMF 4251E
	Policy No.		Coverage (\$)	0.00
	Claim No.	22/23/23/VC05/027424	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	19/05/2023
2.	Vehicle Particulars & Condition			
	Make & Model	HYUNDAI ELANTRA (A)	c.c	1591
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	KMHD841CMJU767367	Colour	METALLIC WHITE
	Odometer	201328 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3.	Conditions of Tyres			
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	MICHELIN	7 mm
	L/H Front Tyre	195/65 R15	MICHELIN	7 mm
	R/H Rear Tyre	195/65 R15	YOKOHAMA	9 mm
	L/H Rear Tyre	195/65 R15	YOKOHAMA	9 mm
4.	Description of Damages			
	THE VEHICLE SUS	STAINED DAMAGES AT THE REA		
5.	General Information			
	Accident Date	17/05/2023	Inspect Date / Time	22/05/2023 (10:17 AM)
	Survey held at	TECK SIANG MOTOR SERVICE		
		BLK 5034 ANG MO KIO INDUSTRIAL PARK 2 #01-331. SINGAPORE 569537		
5a.	Remarks			
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/LPC23005126/Kny3m4

Inspected By

KONG SENG CHEONG

K.K.LAU CPT(RET)

Licensed Appraiser BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser