

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GBD9714U**
 MODEL : **TOYOTA HIACE**
 DATE OF ACCIDENT : 10.05.2023
 TIME OF ACCIDENT : 09:15 HOURS

20	TAILGATE WEATHERSTRIP PROTECTOR <i>Best</i>	1	\$ 198.00	\$ 198.00	✓
21	TAILGATE INNER LOCK <i>Dup</i>	1	\$ 420.00	\$ 420.00	365
22	TAILGATE LOWER LOCK <i>Mem</i>	1	\$ 35.00	\$ 35.00	+
23	TAILGATE DAMPER <i>Mem</i>	2	\$ 110.00	\$ 220.00	+
24	TAILGATE HINGE <i>Mem</i>	2	\$ 55.00	\$ 110.00	+
25	TAILGATE REVERSE CAMERA <i>Mem Dup</i>	1	\$ 1,486.50	\$ 1,486.50	450/50
26	REAR END PANEL (EXTEND) LH <i>Dented</i>	1	\$ 311.10	\$ 311.10	-
27	REAR END PANEL (OUTER) <i>Dented</i>	1	\$ 425.00	\$ 425.00	-
28	REAR END PANEL (INNER) <i>Dented</i>	1	\$ 871.00	\$ 871.00	-
29	REAR END INNER CORNER PANEL LH <i>Rys</i>	1	\$ 446.00	\$ 446.00	+
30	REAR FLOOR PANEL MAT <i>Mem</i>	1	\$ 967.00	\$ 967.00	+
31	REAR FLOOR PANEL <i>Rys</i>	1	\$ 1,960.00	\$ 1,960.00	+
32	REAR SPARE TYRE HOLDER BRACKET <i>3HP</i>	1	\$ 380.00	\$ 380.00	+
33	REAR SPARE TYRE HOLDER BOLT <i>1m</i>	1	\$ 60.00	\$ 60.00	+

821820
 S.N: 450 616365

TOTAL PRICE	\$ 20,075.00
LESS 25%	\$ 5,018.75
SUB TOTAL PRICE	\$ 15,056.25

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>Not rec</i>	1	\$ 80.00	\$ 80.00	+
2	REAR BUMPER CLIP (SET) <i>New</i>	1	\$ 80.00	\$ 80.00	30
3	SIDE PANEL SEALANT <i>New</i>	1	\$ 180.00	\$ 180.00	60
4	REAR SIDE PANEL INNER TRIM CLIP (REAR) LH (SET)	1	\$ 120.00	\$ 120.00	+
5	REAR SIDE INNER LOWER PANEL SEALANT RH <i>Mem</i>	1	\$ 120.00	\$ 120.00	+
6	TAIL LAMP PANEL SEALANT RH <i>Mem</i>	1	\$ 60.00	\$ 60.00	+
7	TAILLAMP INNER PANEL SEALANT RH <i>Mem</i>	1	\$ 60.00	\$ 60.00	+
8	TAILLAMP LOWER GARNISH CLIP RH (SET) <i>Mem</i>	1	\$ 80.00	\$ 80.00	10
9	TAILLAMP INNER COVER GARNISH CLIP RH (SET) <i>Mem</i>	1	\$ 80.00	\$ 80.00	+
10	TAILGATE SEALANT <i>Mem</i>	1	\$ 150.00	\$ 150.00	+
11	TAILGATE INNER TRIM CLIP (SET) <i>New</i>	1	\$ 80.00	\$ 80.00	30
12	TAILGATE OUTER MOULDING CLIP (SET) <i>MW</i>	1	\$ 60.00	\$ 60.00	20
13	TAILGATE STICKER '70KM/H' <i>3HP</i>	1	\$ 30.00	\$ 30.00	15
14	TAILGATE STICKER '5 PAX'	1	\$ 40.00	\$ 40.00	15
15	TAILGATE WINDSCREEN GLASS SEALANT <i>New</i>	1	\$ 80.00	\$ 80.00	40

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GBD9714U**
 MODEL : **TOYOTA HIACE**
 DATE OF ACCIDENT : 10.05.2023
 TIME OF ACCIDENT : 09:15 HOURS

16	TAILGATE WINDSCREEN GLASS INNER SEAL <i>mv</i>	1	\$ 60.00	\$ 60.00 <i>30</i>
17	REAR END PANEL (EXTEND) SEALANT <i>xlw</i>	1	\$ 150.00	\$ 150.00 <i>60</i>
18	REAR END PANEL (OUTER) SEALANT <i>gpi</i>	1	\$ 150.00	\$ 150.00 <i>+</i>
19	REAR END PANEL (INNER) SEALANT <i>n</i>	1	\$ 150.00	\$ 150.00 <i>+</i>
20	REAR END INNER CORNER PANEL SEALANT RH <i>h</i>	1	\$ 80.00	\$ 80.00 <i>+</i>
21	REAR FLOOR PANEL SEALANT <i>mcu</i>	1	\$ 350.00	\$ 350.00 <i>+</i>
22	REAR FLOOR PANEL TOP BOARD (SPECIAL TYPE) <i>h</i>	1	\$ 1,500.00	\$ 1,500.00 <i>+</i>
23	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00 <i>200</i>
			TOTAL	\$ 3,960.00

510

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 2,800.00	<i>1200</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,800.00	<i>1000</i>
3	WIRNING, BULB CHECKING	\$ 180.00	<i>30</i>
4	TRANSFER TAILGATE MECHAISM	\$ 120.00	<i>60</i>
5	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	<i>✓</i>
6	CONDUCT WATER LEAKAGE TEST	\$ 120.00	<i>+</i>
7	REMOVE AND REFIX REAR REVERSE SENSOR	\$ 80.00	<i>50</i>
8	REMOVE AND REFIX STORAGE RACK & FLOOR BOARD	\$ 500.00	<i>280</i>
9	REMOVE AND REFIX AND REWIRING VIDEO CAMERA	\$ 80.00	<i>50</i>
10	REMOVE AND REFIX REVERSE CAMERA	\$ 80.00	<i>50</i>

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GBD9714U**
 MODEL : **TOYOTA HIACE**
 DATE OF ACCIDENT : 10.05.2023
 TIME OF ACCIDENT : 09:15 HOURS

11	REAR CHASSIS ALIGHMENT	\$ 250.00	X
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 160.00	X

TOTAL *2840* 6290

ESTIMATE REPORT

TOTAL PARTS COST : \$ 19,016.25
 TOTAL LABOUR COST : \$ 6,290.00
 TOTAL REPAIR COST : \$ 25,306.25

Admin Lj
L/S 12/05/23
09 Days-

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

total: 9963.65
L/S: 7950

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: