

ASS. REC. BY:

REF:

AGL/ 2300.5130/K943

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

05

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SL E 86 J

Yr Regn:

02, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

LEXUS ES300

c.c

2494

Colour

M. Red

A/C:

Insured / Std / NI / NA

Sp. Reading

156193

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JT4BWIGG 90205354

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

17/5/23

D.O.I.

22/5/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2016 21 PM @ 29501 Colu (Red 6 112.87, 28%)

Date/Time, File Pass to?

1) 20/6 11:54

Date/Time, File Return to?

2)

: Prell. Report

: Final Report

Days Of Repair:

5

Resurvey No. of Trip:

7

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

: Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

Report Format:

TP

Lump Sum / I.B.A. (\$)

2950

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SNB5187K
Accident Date : 17-May-2023

Our Ref : 023110 (AUTO & GEN) / CHAN

CHIN HUI CAR RENTAL
BLK 7 SIN MING IND. ESTATE
SECTOR C, #01-76
Singapore 575642

No. : 06838

Date : 19-May-2023

PAGE : 1

*Not Withheld
1/1 Day @ 2950/
Putty After Paint
5 days*

ESTIMATED COST OF REPAIR FOR LEXUS ES300H SLE86J

1 pc Rear n/s door *1299.50*
1 pc Rear n/s door "HYBRID" plate
1 pc Rear bumper fascia
1 pc Rear n/s bumper side retainer

At/Long

1,299.50

m 82.70

m 1,077.10

m 65.00

2,524.30

Less 10% :

252.43

2,271.87

To putty and spray replaced parts

1,000.00

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

800.00

Total : S\$ 4,071.87

Singapore Dollars Four Thousand and Seventy One
and Cents Eighty Seven Only

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: