

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| | Reg. No: 19960/198R GST Reg. No. 19-960/198-R | | | | |
|---|---|--|-----------------|---------------------------|--|
| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
| | AUTO & GENERA | L INSURANCE (S) PL | Re | ef: CS/AGI23005131/Kvy3e2 | |
| | (BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924 | INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE | Da | ate: 29/05/2023 | |
| | | | Со | ode: AGI | |
| 1. | 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | SKZ 2770E | Veh. Inspected | SHD 9939S | |
| | Policy No. | P10673599R01 | Coverage (\$) | 0.00 | |
| | Claim No. | C10022263/CD | Excess (\$) | 0.00 | |
| | Assign From | MAYBIE CHUA | Assign Date | 19/05/2023 | |
| 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | TOYOTA PRIUS (A) | c.c | 1798 | |
| | Engine No. | HIDDEN | Year of Reg. | 2021 | |
| | Chassis No. | JTDKB3FU203093391 | Colour | M.P. WHITE / RED | |
| | Odometer | 204372 KM | Steering | IN ORDER | |
| | Brakes | IN ORDER | Modification | STANDARD ALLOY RIM | |
| | General | GOOD | | | |
| 3. | Conditions of Tyres | | | | |
| | | Size | Make | Balance | |
| | R/H Front Tyre | 195/65 R15 | WANLI | 8 mm | |
| | L/H Front Tyre | 195/65 R15 | WANLI | 8 mm | |
| | R/H Rear Tyre | 195/65 R15 | WANLI | 3 mm | |
| | L/H Rear Tyre | 195/65 R15 | WANLI | 3 mm | |
| 4. | Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. | | | | |
| | DAMAGES SEE DETAILS. | | | | |
| 5. | General Information | | | | |
| | Accident Date | 12/05/2023 | Inspection Date | 22/05/2023 | |
| | Survey held at | TRANS-CAB AUTO SERVICES | PTE LTD | | |
| | | NO.2 ANG MO KIO ST 63 SINGAPORE 569111 | | | |
| 5a. | Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. | Estimate Days of Repair | | | | |

2 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: