

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23005148/RNP3Q2**Date:** 03/07/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00112162201
Claimant Vehicle No :	SMF233J	Insured Vehicle No :	GBF4141U
Date of Loss:	30/04/2023	Nature of Claim: TP	Claim No: SNM23D203140/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF233J	Engine No:	G4FGJH703969
Make & Model:	KIA CERATO, 1.6 SX (A)	Chassis No:	KNAF3416MK5013617
Reg. Date:	21/09/2018 (Man. Year: 2018)	Odometer:	72478 km
Colour:	White		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,183.00	3,131.00	52.00	1.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,220.00	1,670.00	2,550.00	60.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,403.00	4,801.00	2,602.00	35.15
+ GST 8.00/8.00% (S\$)	592.24	384.08	208.16	35.15
Nett Amount (S\$)	7,995.24	5,185.08	2,810.16	35.15

INSPECTION

Date of Assignment:	19/05/2023	
Date Inspected:	12/06/2023	Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Jul 2023)
Parts:	143	KIA CERATO 1.6 SX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMF233J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*LAMP ASSY -HEAD RH	Scratched	2,210.00 FS	*2,210.00 FS
3	1		*COVER -FR BUMPER	Deformed	665.00 FS	*665.00 FS
4	1		*MOULDING -FRONT BUMPER, RH	Deformed	90.00 FS	*90.00 FS
5	1		*AIR DUCT -FR BUMPER ,RH	Deformed	14.00 FS	*14.00 FS
6	1		*ABSORBER -FRONT BUMPER ENERGY	Cracked	84.00 FS	*84.00 FS
7	1		*BRACKET -FR BUMPER UPR SIDE MTG	Not Necessary	22.00 FS	*- FS
8	1		*ORNAMENT -KIA NO.115	Necessary	38.00 FS	*38.00 FS
9	10		*CLIP	Necessary	10.00 FS	*10.00 FS
Total Parts (S\$)						3,183.00
						3,131.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER PANEL ,FRT RH HEADLAMP & AFFECTED AREA REPAIR ON FRT RH FENDER	New	1,920.00	640.00
2	PAINT WORK ON FRT BUMPER PANEL & FRT RH FENDER	New	1,650.00	550.00
3	PERFORM RUST PROVENTION	New	100.00	0.00
4	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	120.00	100.00
5	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	280.00	280.00
6	REMOVE & INSTALL FRT PARKING ASSIST FOR FACILITATE REPAIR	New	150.00	100.00
Gross Labour Cost (S\$)			4,220.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >