

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Page No.:1 of 1

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT HSBC LIFE (SINGAPORE) PTE LTD CS3/HSB23005150/Uqp3m4 Ref: 10 MARINA BOULEVARD #48-01 MARINA BAY Date: 03/07/2023 FINANCIAL CENTRE TOWER 2SINGAPORE ATTN: OH VALE Code: HSB Policy Particulars :- (THIRD PARTY CLAIM) 1. SH 7248P JTQ 7205 Insured Veh. Veh. Inspected VFX/P2419138 0.00 Policy No. Coverage (\$) S3M04MO9 0.00 Claim No. Excess (\$) 22/05/2023 OH VALE **Assign Date** Assign From Vehicle Particulars & Condition 2. HONDA PCX 149 Make & Model C.C **HIDDEN Engine No.** Year of Reg. 2019 PMKKF3170JB001558 WHITE Chassis No. Colour Odometer 48973 KM **AFFECTED** Steering **IN ORDER** SPORTS RIM Modification **Brakes** FAIR General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre TIMSUN 100/80-14 7 mm L/H Front Tyre mm 110-80-14 TIMSUN R/H Rear Tyre 7 mm L/H Rear Tyre mm **Description of Damages** 4. THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND N/S BODY. 5. **General Information** 18/05/2023 **Inspect Date / Time** 22/05/2023 (11:15 AM) **Accident Date** 25 KAKI BUKIT ROAD 4 #03-79 SINGAPORE 417800 Survey held at **EQBH PTE LTD** Repairer 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500-\$3,000

Report Ref No. CS3/HSB23005150/Uqp3m4

Estimate Days of Repair

Inspected By

ESTIMATED NORMAL PERIOD FOR REPAIR:

5b.

CHUA KANG SENG Licensed Appraiser K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

4 Working Days

REGD Auto Consultant-SAE, Licensed Appraiser