

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23005167/AVP3M4
Date: 10/07/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00141442202	
Claimant Vehicle No :	SJA4610P	Insured Vehicle No :	GY5850R	
Date of Loss:	17/05/2023	Nature of Claim:	TP	Claim No: SNM23D203557/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJA4610P		Engine No:	Z6594702
Make & Model:	MAZDA 3, 1.6 SP (A)		Chassis No:	JM6BK106280368086
Reg. Date:	11/12/2007 (Man. Year: 2007)		Odometer:	187351 km
Colour:	Red			
Engine Capacity:	1598 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,956.56	3,934.96	3,021.60	43.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,990.00	1,270.00	1,720.00	57.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,946.56	5,204.96	4,741.60	47.67
Approved Total (Overridden) (S\$)		4,150.00		
Nett Amount (S\$)	9,946.56	4,150.00	5,796.56	58.28

INSPECTION

Date of Assignment:	22/05/2023		
Date Inspected:	18/05/2023	Inspected At:	AUTOMOBILE HUB ENTERPRISE 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 Jul 2023)
Parts: 143	MAZDA 3 1.6 SP (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJA4610P)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	976.20 FL	*976.20 FL
2	1		*FRONT BUMPER SIDE HOLDER	Damaged	28.70 FL	*28.70 FL
3	1		*FRONT BUMPER LOWER SPOILER	Cracked	550.40 FL	*550.40 FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	548.40 FL	*- FL
5	1		*FRONT BUMPER SIDE GRILLE	Not Necessary	100.20 FL	*- FL
6	1		*FRONT BUMPER LOWER GRILLE	Cracked	123.80 FL	*123.80 FL
7	1		*FRONT BUMPER UNDERCOVER	Torn	96.50 FL	*96.50 FL
8	1		*FRONT GRILLE	Cracked	382.10 FL	*382.10 FL
9	1		*FRONT GRILLE LOGO	Necessary	54.90 FL	*54.90 FL
10	2		*HEADLAMP	Cracked	1,951.80 FL	*1,951.80 FL
11	2		*HEADLAMP LOWER BRACKET	Not Necessary	107.60 FL	*- FL
12	1		*BONNET	Repair	920.60 FL	*- FL
13	1		*FRONT SUPPORT PANEL	Not Necessary	585.80 FL	*- FL
14	1		*FRONT FENDER	Dented	398.10 FL	*398.10 FL
15	1		*FRONT FENDER INNER SHIELD	Deformed	175.40 FL	*175.40 FL
16	1		*FRONT FENDER BRACKET	Bent	55.80 FL	*55.80 FL
17	1		*FRONT DOOR WING MIRROR	Not Necessary	389.40 FL	*- FL
18	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
19	1		*SET FRONT BUMPER UNDERCOVER CLIPS	Necessary	20.00 FS	*20.00 FS
20	1		*SET FRONT GRILLE CLIPS	Necessary	20.00 FS	*20.00 FS
21	1		*COOLANT	Not Necessary	50.00 FS	*- FS
22	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	30.00 FS	*30.00 FS
23	1		*FRONT WHEEL RIM	Not Necessary	850.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,445.70	4,893.70
- List Item Discount on L Items 20.00/20.00% (S\$)	1,489.14	958.74
Total Parts (S\$)	6,956.56	3,934.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVE AND REFIT PARTS	New	1,200.00	600.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,200.00	600.00
3	WIRING CHECK	New	50.00	30.00
4	TO APPLY TUFF COAT	New	150.00	40.00
5	TO PERFORM WHEEL ALIGNMENT	New	150.00	0.00
6	TO REMOVE CONDENSER & TO TOP UP AIR CON GAS	New	120.00	0.00
7	TO REMOVE RADIATOR & TO TOP UP COOLANT	New	120.00	0.00
Gross Labour Cost (S\$)			2,990.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >