

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG23005182/UQP3M4**Date:** 31/05/2023**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1002099884
Claimant Vehicle No :	SNH7485E	Insured Vehicle No :	GBD3134H
Date of Loss:	18/05/2023	Nature of Claim:	TP
		Claim No:	314973

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNH7485E	Engine No:	0
Make & Model:	BYD E6 (ME-2), (A)	Chassis No:	LC0CE4DC0N0269994
Reg. Date:	24/11/2022 (Man. Year: 2022)	Odometer:	22105 km
Colour:	Black		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55R17	Rear Tyre Size:	215/55R17
Front Left Side:	CHAO YANG 7 mm	Rear Left Side:	CHAO YANG 7 mm
Front Right Side:	CHAO YANG 7 mm	Rear Right Side:	CHAO YANG 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,048.06	4,631.90	15,416.16	76.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,270.00	1,220.00	2,050.00	62.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,318.06	5,851.90	17,466.16	74.90
Approved Total (Overridden) (S\$)		4,600.00		
(S\$)	23,318.06	4,600.00	18,718.06	80.27
+ GST 8.00/8.00% (S\$)	1,865.44	368.00	1,497.44	80.27
Nett Amount (S\$)	25,183.50	4,968.00	20,215.50	80.27

INSPECTION

Date of Assignment:	23/05/2023		
Date Inspected:	22/05/2023	Inspected At:	CARSMITH PTE LTD BARTLEY BIZ CENTRE, 13 KAKI BUKIT ROAD 4 #01-20 SINGAPORE 417807
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 May 2023)
Parts:	M1-MPV	BYD E6 (ME-2) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNH7485E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER TOP	Dented/Deformed	1,405.00 FL	*1,350.00 FL
2	1		*REAR BUMPER BOTTOM	Deformed	1,380.00 FL	*480.00 FL
3	1		*REAR BUMPER RETAINER LH	Not Necessary	87.00 FL	*- FL
4	1		*REAR BUMPER RETAINER RH	Not Necessary	87.00 FL	*- FL
5	1		*RAR BUMPER BRACKET LH	Not Necessary	87.00 FL	*- FL
			REAR BUMPER BRACKET LH INSTEAD OF RAR			
6	1		*RAR BUMPER BRACKET RH	Not Necessary	87.00 FL	*- FL
			REAR BUMPER BRACKET RH INSTEAD OF RAR			
7	1		*REAR BUMPER GRILLE BAR LH	Not Necessary	85.00 FL	*- FL
8	1		*REAR BUMPER GRILLE BAR RH	Not Necessary	85.00 FL	*- FL
9	1		*REAR BUMPER GRILLE BAR CENTER	Repair	124.00 FL	*- FL
10	1		*REAR REFLECTOR LH	Not Necessary	198.00 FL	*- FL
11	1		*REAR REFLECTOR RH	Not Necessary	198.00 FL	*- FL
12	1		*REAR REFLECTOR CENTRE	Not Necessary	425.00 FL	*- FL
13	1		*REAR END PANEL	Repair	852.00 FL	*- FL
14	1		*REAR END PANEL TOP GARNISH	Not Necessary	287.00 FL	*- FL
15	1		*REAR REINFORCEMENT	Repair	565.00 FL	*- FL
16	2		*REAR REINFORCEMENT BRACKET	Not Necessary	352.00 FL	*- FL
17	1		*SPARE TYRE SPONGE	Not Necessary	247.00 FL	*- FL
18	1		*SPARE TYRE HOLDER	Not Necessary	425.00 FL	*- FL
19	1		*FLOOR PANEL	Not Necessary	324.00 FL	*- FL
20	1		*THIRD BRAKE LAMP	Not Necessary	327.00 FL	*- FL
21	1		*WINDSCREEN	Not Necessary	857.00 FL	*- FL
22	1		*WINDSCREEN MOULDING	Not Necessary	472.00 FL	*- FL
23	1		*WIPER	Not Necessary	135.00 FL	*- FL
24	1		*WIPER MOTOR	Not Necessary	575.00 FL	*- FL
25	1		*TAILGATE	Badly Dented	5,459.40 FL	*3,201.00 FL
26	1		*TAILGATE LOCK	Not Necessary	578.00 FL	*- FL
27	1		*TAILGATE WEATHERSTRIP	Not Necessary	373.00 FL	*- FL
28	2		*TAILGATE HINGE	Not Necessary	176.00 FL	*- FL
29	1		*TAILGATE LAMP LH	Not Necessary	458.00 FL	*- FL
30	1		*TAILGATE LAMP RH	Not Necessary	458.00 FL	*- FL
31	1		*TAILGATE LOGO	Not Necessary	108.00 FL	*- FL
32	1		*TAILGATE EMBLEM BYD E6	Necessary	108.00 FL	*60.00 FL
33	1		*TAILGATE CHROME MOULDING	Not Necessary	345.00 FL	*- FL
34	1		*TAILGATE INNER TRIM BOARD	Not Necessary	358.00 FL	*- FL
35	1		*TAILLAMP LH	Not Necessary	783.00 FL	*- FL
36	1		*TAILLAMP RH	Not Necessary	783.00 FL	*- FL
37	1		*TAILLAMP BRACKET LH	Not Necessary	275.00 FL	*- FL
38	1		*TAILLAMP BRACKET RH	Not Necessary	275.00 FL	*- FL
39	1		*TAILLAMP CHROME MOULDING LH	Not Necessary	175.00 FL	*- FL
40	1		*TAILLAMP CHROME MOULDING RH	Not Necessary	175.00 FL	*- FL
41	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
42	1		*REAR NUMBER PLATE W/GARNISH	Not Necessary	90.00 FS	*- FS
43	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
44	1		*REVERSE CAMERA	Not Necessary	480.00 FS	*- FS
45	1		*REVERSE SENSOR	Serviceable	480.00 FS	*- FS

Report was unsubmitted during this print-out.

5/31/23, 9:55 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*REVERSE SENSOR HOLDER	Not Necessary	80.00 FS	*- FS
47	1		*COMPANY STICKER	Not Necessary	200.00 FS	*- FS
48	1		*JOINT SEALANT	Not Necessary	120.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$\$)	22,103.40
					5,141.00	
					- List Item Discount on L Items 10.00/10.00% (\$\$)	2,055.34
						509.10
					Total Parts (\$\$)	20,048.06
						4,631.90
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK ACCIDENT AFFECTED AREA WIRING AND LIGHTING SYSTEM	New	150.00	20.00
2	REMOVE AND REFIT REAR WINDSCREEN TO FACILITATE REPAIR	New	200.00	120.00
3	REMOVE AND RENEW REAR REVERSE SENSOR	New	120.00	50.00
4	REMOVE AND REFIT REAR ACCIDENT AFFECTED AREA LINING, TRIM AND GARNISH	New	200.00	0.00
5	PANEL BEATING ON REAR ACCIDENT AFFECTED AREAS AND RENEW DAMAGE PARTS	New	1,200.00	400.00
6	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS	New	1,200.00	600.00
7	APPLY ANTI RUST ON ACCIDENT AFFECTED AREAS	New	200.00	30.00
Gross Labour Cost (S\$)			3,270.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >