

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIS23005184/TQP3E2
Date: 26/07/2023REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	
Claimant Vehicle No :	GBK1005Z	Insured Vehicle No :	GBK2934K
Date of Loss:	18/05/2023	Nature of Claim:	TP Claim No: GBK2934K

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBK1005Z	Engine No:	1KDB019134
Make & Model:	TOYOTA HIACE, 3.0 (A)	Chassis No:	JTFHT02PX00250048
Reg. Date:	20/12/2019 (Man. Year: 2019)	Odometer:	100529 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,784.25	2,594.12	9,190.13	77.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,690.00	1,540.00	2,150.00	58.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,474.25	4,134.12	11,340.13	73.28
Approved Total (Overridden) (\$\$)		3,300.00		
(\$\$)	15,474.25	3,300.00	12,174.25	78.67
+ GST 8.00/8.00% (\$\$)	1,237.94	264.00	973.94	78.67
Nett Amount (\$\$)	16,712.19	3,564.00	13,148.19	78.67
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	22/05/2023	
Date Inspected:	22/05/2023	Inspected At: S Three Automotive Recovery Pte Ltd (HQ) Blk 8 Sin Ming Industrial Estate, #01-64/66 Sector C Singapore 575643
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Jul 2023)	
Parts:	N/A	TOYOTA HIACE 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK1005Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,921.00 F	*1,698.00 FL
2	1		*TAILGATE GLASS	Cracked	850.00 F	*850.00 FL
3	1		*TAILGATE GLASS MOULDING	Necessary	180.00 F	*180.00 FL
4	1		*REAR TAILGATE LOGO	Necessary	65.70 F	*65.70 FL
5	1		*REAR TAILGATE TOYOTA EMBLEM	Necessary	48.50 F	*48.50 FL
6	1		*REAR TAILGATE HIACE EMBLEM	Necessary	48.50 F	*48.50 FL
7	1		*REAR TAILGATE OUTER HANDLE	Not Necessary	238.00 F	*- FL
8	1		*REAR TAILGATE INNER BOARD	Not Necessary	425.80 F	*- FL
9	1		*REAR WIPER BLADE	Not Necessary	95.00 F	*- FL
10	1		*REAR TAILLAMP LH	Not Necessary	650.00 F	*- FL
11	1		*REAR TAILLAMP RH	Cracked	650.00 F	*354.80 FL
12	1		*REAR TAILLAMP LOWER GARNISH LH	Not Necessary	180.00 F	*- FL
13	1		*REAR TAILLAMP LOWER GARNISH RH	Repair	180.00 F	*- FL
14	1		*REAR END PANEL TOP ALUMINIUM	Not Necessary	390.00 F	*- FL
15	1		*REAR BUMPER	Repair	580.00 F	*- FL
16	1		*REAR BUMPER BRACKET LH	Not Necessary	65.00 F	*- FL
17	1		*REAR BUMPER BRACKET RH	Not Necessary	65.00 F	*- FL
18	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	45.00 F	*- FL
19	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	45.00 F	*- FL
20	1		*REAR END INNER PANEL	Not Necessary	850.00 F	*- FL
21	1		*REAR FENDER LH	Repair	1,411.95 F	*- FL
22	1		*REAR NUMBER PLATE LAMPS	Not Necessary	79.80 F	*- FL
23	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
24	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
25	1		*SET REAR END PANEL GARNISH CLIPS	Not Necessary	80.00 FS	*- FS
26	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
27	1		*REVERSE SENSOR	Not Necessary	350.00 FS	*- FS
28	1		*TAILGATE STICKER 70	Necessary	50.00 FS	*15.00 FS
29	1		*TAILGATE STICKER 8PAX	Necessary	50.00 FS	*15.00 FS
30	1		*WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
31	1		*WINDSCREEN INNER SEAL	Necessary	50.00 FS	*30.00 FS
32	1		*WINDSCREEN PRIMER & CLEANER	Necessary	50.00 FS	*30.00 FS
33	1		*REVERSE CAMERA	Not Necessary	1,800.00 FS	*- FS
					Sub Total (\$\$)	11,784.25 3,405.50
					- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00 811.38
					Total Parts (\$\$)	11,784.25 2,594.12

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	STRAIGHTEN & PANEL BEAT ACCIDENT AREAS	New	1,600.00	600.00
2	SPRAY PAINTING ON ACCIDENT AREAS	New	1,400.00	700.00
3	RESPRAY KUFF TOTE ON ACCIDENT AREAS	New	120.00	0.00
4	R&R TAILGATE COMPONENTS	New	150.00	60.00
5	R&R REVERSE SENSOR SYSTEM	New	120.00	30.00
6	R&R WINDSCREEN GLASS	New	150.00	120.00
7	CHECK WIRING SYSTEM AND ASSIST REPAIR	New	150.00	30.00
Gross Labour Cost (\$)			3,690.00	1,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >