

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI23005190/UVP3Q2**Date:** 06/07/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00267222202

**Claimant Vehicle No :** SMU4729R **Insured Vehicle No :** SDU11K

Date of Loss: 08/05/2023 Nature of Claim: TP Claim No: SNM23D203341/C02/TAYHP

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMU4729R**

Make & Model: MERCEDES-BENZ E250, 1.8 (A) Engine No: 27492030086213

Reg. Date: 18/12/2013 (Man. Year: 2013) Chassis No: WDD2120362A845926

Colour: Silver Odometer: 167991 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 245/40Z R18 Rear Tyre Size: 245/40Z R18

Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm

Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,076.50	1,363.50	713.00	34.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	810.00	450.00	360.00	44.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,886.50</b>	<b>1,813.50</b>	<b>1,073.00</b>	<b>37.17</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,450.00</b>		
<b>(S\$)</b>	2,886.50	1,450.00	1,436.50	49.77
<b>+ GST 8.00/8.00% (S\$)</b>	230.92	116.00	114.92	49.77
<b>Nett Amount (S\$)</b>	<b>3,117.42</b>	<b>1,566.00</b>	<b>1,551.42</b>	<b>49.77</b>

**INSPECTION**

Date of Assignment: 23/05/2023

Date Inspected: 23/05/2023 Inspected At: TLM Automobile Pte Ltd (HQ)  
1 Defu Lane 6  
Singapore 539365

Estimated Period of Repair: 2.0 days

**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jul 2023)
Parts:	143	MERCEDES-BENZ E250 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU4729R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deep Cut	1,515.00 FN	*1,515.00 FN
2	1		*O/S FRONT BUMPER SIDE BRACKET	Not Necessary	50.00 FN	*- FN
3	1		*O/S FRONT BUMPER LOWER GRILLE	Not Necessary	120.00 FN	*- FN
4	2		*FRONT BUMPER PARKING SENSOR	Serviceable	560.00 FS	*- FS
					Sub Total (S\$)	2,245.00 1,515.00
					- Nett Item Discount on N Items 10.00/10.00% (S\$)	168.50 151.50
					Total Parts (S\$)	2,076.50 1,363.50

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REINSTALL OF FRONT BUMPER PARKING SENSOR	New	80.00	50.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	30.00	0.00
3	TO RUST -PROOFING OF THE AFFECTED AREAS	New	50.00	0.00
4	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	300.00	200.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	350.00	200.00
<b>Gross Labour Cost (S\$)</b>			<b>810.00</b>	<b>450.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >