

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23005191/UQP3M4**Date:** 13/07/2023**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00094102202

**Claimant Vehicle
No :** SNF3974Y**Insured
Vehicle No :** GBF2967S

Date of Loss: 19/05/2023

Nature of Claim: TP

Claim
No: SNM23D203597/C02/TAYHP**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SNF3974Y**Make & Model: BMW 535I, 3.0 L D/AB 2WD 4DR GAS/D SR
HUD (A)

Engine No: 07147617N55B30A

Reg. Date: 15/12/2010 (Man. Year: 2010)

Chassis No: WBAFR72030C580586

Colour: White

Odometer: 174971 km

Engine Capacity: 2979 cc

Market Value/New Car
Price: N/ASum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/35 ZR19

Rear Tyre Size: 275/35 ZR19

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,224.52	7,715.00	2,509.52	24.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,240.00	990.00	1,250.00	55.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,464.52	8,705.00	3,759.52	30.16
Approved Total (Overridden) (S\$)		6,900.00		
(S\$)	12,464.52	6,900.00	5,564.52	44.64
+ GST 8.00/8.00% (S\$)	997.16	552.00	445.16	44.64
Nett Amount (S\$)	13,461.68	7,452.00	6,009.68	44.64

INSPECTION

Date of Assignment: 10/07/2023

Date Inspected: 23/05/2023 Inspected At:

BLUWEL AUTOMOTIVE SERVICE PL
BLK 1 KAKI BUKIT AVE 6
#01-28/53/55/56 SINGAPORE 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jul 2023)
Parts:	143	BMW 535I 3.0 L D/AB 2WD 4DR GAS/D SR HUD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNF3974Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,499.30 FN	*1,499.30 FN
2	1		*FRONT BUMPER REINFORCEMENT	Serviceable	615.00 FN	*- FN
3	1		*FRONT BUMPER SPONGE	Torn	162.80 FN	*162.80 FN
4	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FN	*50.00 FN
5	1		*FRONT BUMPER RETAINER	Not Necessary	158.80 FN	*- FN
6	2		*FRONT BUMPER SIDE RETAINERS	Not Necessary	219.40 FN	*- FN
7	1		*FRONT BUMPER LOGO	Necessary	105.00 FN	*105.00 FN
8	1		*FRONT BUMPER PDC SENSOR	Malfunction	175.00 FN	*175.00 FN
9	1		*FRONT GRILLE O/S	Cracked	162.00 FN	*162.00 FN
10	1		*BONNET	Dented/Warped	2,378.95 FN	*2,378.95 FN
11	1		*BONNET LOCK	Not Necessary	198.70 FN	*- FN
12	1		*FRONT SUPPORT PANEL	Repair	469.70 FN	*- FN
13	1		*HEADLAMP O/S	Cracked	3,102.00 FN	*3,102.00 FN
14	1		*HEADLAMP LOWER BRACKET O/S	Cracked	223.00 FN	*223.00 FN
15	1		*AIR DUCT GARNISH	Torn	263.00 FN	*263.00 FN
16	1		*CONDENSER	Not Necessary	980.00 FN	*- FN

F=Franchise part. N=NettItemDisc.

Sub Total (S\$)	10,762.65	8,121.05
- Nett Item Discount on N Items 5.00/5.00% (S\$)	538.13	406.05
Total Parts (S\$)	10,224.52	7,715.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	50.00	30.00
3	TO DISMANTLE & REPLACED FRONT PDC SENSOR	New	80.00	40.00
4	TO RESET & REPROGRAMME SYSTEM	New	180.00	0.00
5	TO REFILL AIR CON GAS	New	120.00	0.00
6	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	680.00	400.00
7	TO PUTTY & SPRAY PAINTING	New	1,080.00	500.00
Gross Labour Cost (S\$)			2,240.00	990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >