

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTERGO Insurance Pte. Ltd.
8 Temasek Boulevard, #04-01 Suntec Tower Three
Singapore 038988**Our File No:** CS/EGI23005200/KVP3E2**Date:** 25/07/2023**REFERENCE**

Insured/Claimant:	CHEONG JUN YU	Policy No:	DMPG23005338		
Date of Loss:	20/05/2023	Nature of Claim:	OD	Claim No:	CDMPG23001241

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKK88J		
Make & Model:	MERCEDES-BENZ S450L, 3.0 R19 LED (A)	Engine No:	27682430784697
Reg. Date:	19/04/2018 (Man. Year: 2017)	Chassis No:	WDD2221662A384160
Colour:	Metallic Dark Grey	Odometer:	119766 km
Engine Capacity:	2996 cc		
Market Value/New Car Price:	S\$254,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/45 R19	Rear Tyre Size:	275/40 R19
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,930.08	10,390.18	8,539.90	45.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,405.00	1,460.00	1,945.00	57.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,335.08	11,850.18	10,484.90	46.94
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
Nett Amount (S\$)	21,335.08	10,850.18	10,484.90	49.14

INSPECTION

Date of Assignment:	23/05/2023		
Date Inspected:	23/05/2023	Inspected At:	Lim Yew Boo Spray Paint Co (HQ) Blk 10 Sin Ming Industrial Estate, #01-10 Singapore 575645
Estimated Period of Repair:	6.0 days		

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 25 Jul 2023)
Parts: 143	MERCEDES-BENZ S450L 3.0 R19 LED (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKK88J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Buckled	1,580.00 F	*1,580.00 F
2	1		*FRONT BUMPER RETAINER/RH (WCP)	Serviceable	15.00 F	*- F
3	1		*FRONT BUMPER BRACKET/RH (WCP)	Serviceable	15.00 F	*- F
4	1		*FRONT BUMPER INSIDE PART (SIDE) (WCP)	Cracked	317.00 F	*317.00 F
5	1		*FRONT BUMPER SPONGE (WCP)	Serviceable	191.00 F	*- F
6	1		*FRONT BUMPER TOWING COVER/RH (WCP)	Serviceable	61.00 F	*- F
7	1		*FRONT BUMPER LOWER GRILLE/RH (WCP)	Missing	121.00 F	*121.00 F
8	1		*FRONT BUMPER LOWER GRILLE CHROME/RH (WCP)	Missing	163.00 F	*163.00 F
9	1		*FRONT FENDER/RH (WCP)	Bent	659.00 F	*659.00 F
10	1		*FRONT FENDER INNER SHIELD/RH (WCP)	Distorted	185.00 F	*160.00 F
11	1		*FRONT GRILLE (WCP)	Serviceable	750.00 F	*- F
12	1		*FRONT HEADLAMP/RH (WCP)	Cracked	4,515.00 F	*4,515.00 F
13	1		*FRONT HEADLAMP LOWER BRACKET/RH (WCP)	Cracked	45.00 F	*45.00 F
14	1		*FRONT HEADLAMP CONTROL UNIT/RH (WCP)	Serviceable	400.00 F	*- F
15	1		*FRONT SENSOR (WCP)	Serviceable	195.00 F	*- F
16	1		*FRONT SENSOR HOLDERS (WCP)	Serviceable	15.00 F	*- F
17	1		*FRONT SENSOR WIRE HARNESS (WCP)	Serviceable	300.00 F	*- F
18	1		*FRONT WIPER TANK (WCP)	Dented	165.00 F	*165.00 F
19	1		*FRONT AIR-CON PIPE (IN) (WCP)	Serviceable	435.00 F	*- F
20	1		*FRONT AIR-CON PIPE (OUT) (WCP)	Bent	195.00 F	*195.00 F
21	1		*FRONT ABSORBER/RH (WCP)	Serviceable	2,200.00 F	*- F
22	1		*FRONT LOWER ARM/RH (WCP)	Serviceable	454.00 F	*- F
23	1		*FRONT KNUCKLE ARM/RH (WCP)	Serviceable	1,020.00 F	*- F
24	1		*FRONT BEARING HUP/RH (WCP)	Serviceable	420.00 F	*- F
25	1		*FRONT BUMPER LOWER GRILLE/CENTRE (WCP)	Serviceable	111.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1		*FRONT BUMPER LOWER GRILLE CHROME/RH (WCP)	Serviceable	161.00 F	*- F
27	10		*FRONT FENDER INNER SHIELD CLIP/RH	Necessary	50.00 FS	*50.00 FS
28	10		*RIVERTS 003 990 9497MB	Necessary	50.00 FS	*50.00 FS
29	1		*GST BY SUPPLIER		669.28 FS	*669.28 FS
30	1		*FRONT HOSE LINE (WCP)	Torn	166.00 F	*166.00 F
31	1		*FRONT HEADLAMP PANEL (WCP)	Cracked	280.00 F	*280.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$)	15,903.28	9,135.28
+ Margin on L,N Items 20.00/15.00% (\$)	3,026.80	1,254.90
Total Parts (\$)	18,930.08	10,390.18

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER FRONT SENSORS TO NEW BUMPER	New	60.00	60.00
2	TO CHECK / REPAIR / REPLACE ON WIRE HARNESS	New	120.00	80.00
3	TO VACUUM & TOP UP AIR-CON GAS	New	80.00	0.00
4	TO FOCUS HEADLAMP & CHECK HEADLAMP WIRING FUNCTION	New	55.00	20.00
5	TO RE-SET ABS SYSTEM & ERASE REGISTERED FAULT	New	120.00	0.00
6	TO CHECK ON COMPUTERISE ALIGNMENT	New	120.00	0.00
7	TO CHECK / REPAIR / REPLACE THE AFFECTED AIR-CON PIPE	New	180.00	0.00
8	TO VACUUM & TOP UP AIR-CON GAS	New	120.00	0.00
9	LABOUR TO CHECK /REPAIR / REPLACE RIGHT UNDER CARRIAGE AFFECTED PARTS	New	350.00	0.00
10	TO REPAIR, PANEL BEAT, RE-STRAIGHTEN ON AFFECTED PANEL, BONNET & LABOUR TO REPLACE ABOVE PARTS	New	1,000.00	550.00
11	TO PUTTY, PRIMER & SPRAY PAINT ON RIGHT FRT FENDER, FRT BUMPER, SENSOR & TOUCH UP ON AFFECTED BONNET ONLY	New	1,000.00	750.00
12	LABOUR TO REPLACE THE ABOVE PARTS	New	200.00	0.00
			Gross Labour Cost (\$)	3,405.00
				1,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >