

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

HL Assurance Pte Ltd
11 Keppel Road, #11-01 ABI Plaza
Singapore 089057

Our File No: CS/HLA23005213/KQP3Q2**Date:** 18/07/2023**REFERENCE**

Insured/Claimant:	LIM KIA WEE (LIN JIAWEI)	Policy No:	MP308804
Date of Loss:	21/05/2023	Nature of Claim:	OD Claim No: MPC04277

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU7035B		
Make & Model:	AUDI A4, 1.4 TFSI S TRONIC (A)	Engine No:	CVN044761
Reg. Date:	07/12/2017 (Man. Year: 2017)	Chassis No:	WAUZZZF46JA021049
Colour:	Metallic Grey	Odometer:	139448 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$93,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,228.40	6,351.10	2,877.30	31.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,750.00	1,160.00	590.00	33.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,978.40	7,511.10	3,467.30	31.58
- Excess (\$\$)	0.00	600.00	-600.00	
(\$\$)	10,978.40	6,911.10	4,067.30	37.05
+ GST 8.00/8.00% (\$\$)	878.27	552.89	325.38	37.05
Nett Amount (\$\$)	11,856.67	7,463.99	4,392.68	37.05

INSPECTION

Date of Assignment:	23/05/2023	Present Location:	Alan's United Auto Pte Ltd (HQ)
Date Inspected:	24/05/2023	Inspected At:	Alan's United Auto Pte Ltd (HQ) Blk 7 Sin Ming Industrial Estate, #01-76 Singapore 575642
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Jul 2023)
Parts:	143	AUDI A4 1.4 TFSI S TRONIC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU7035B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER FASCIA (WCP)	Cracked	900.00 F	*900.00 F
2	1		*FRONT LH BUMPER INNER PARTS (WCP)	Cracked	82.00 F	*82.00 F
3	1		*FRONT LH BUMPER INNER PARTS CLIP (SET) (WCP)	Not Necessary	36.00 F	*- F
4	1		*FRONT LH BUMPER NOZZLE COVER (WCP)	Dented	72.00 F	*72.00 F
5	1		*FRONT LH BUMPER NOZZLE COVER SPRING (WCP)	Not Necessary	28.00 F	*- F
6	1		*FRONT LH BUMPER NOZZLE (WCP)	Cracked	190.00 F	*190.00 F
7	1		*FRONT LH BUMPER NOZZLE BRACKET (WCP)	Cracked	25.00 F	*25.00 F
8	1		*FRONT LH BUMPER NOZZLE HOSE (WCP)	Serviceable	155.00 F	*- F
9	1		*FRONT LH BUMPER GRILLE (WCP)	Missing	130.00 F	*130.00 F
10	1		*FRONT BUMPER UNDER COVER (WCP)	Serviceable	195.00 F	*- F
11	1		*FRONT BUMPER REINFORCEMENT (WCP)	Repair	450.00 F	*- F
12	1		*FRONT LH BUMPER REINFORCEMENT SUPPORT (WCP)	Serviceable	195.00 F	*- F
13	1		*FRONT BUMPER SPONGE (WCP)	Serviceable	130.00 F	*- F
14	1		*FRONT SUPPORT TOP COVER (WCP)	Serviceable	125.00 F	*- F
15	1		*FRONT LH FENDER (WCP)	Buckled	420.00 F	*420.00 F
16	1		*FRONT LH FENDER LOWER BRACKET (WCP)	Repair	36.00 F	*- F
17	1		*FRONT LH FENDER INNER SUPPORT (WCP)	Serviceable	90.00 F	*- F
18	1		*FRONT LH FENDER INNER LOWER BRACKET (WCP)	Repair	55.00 F	*- F
19	1		*FRONT LH FENDER FRONT BRACKET (WCP)	Cracked	72.00 F	*72.00 F
20	1		*FRONT LH FENDER INNER SHIELD (WCP)	Distorted	185.00 F	*185.00 F
21	1		*FRONT LH FENDER INNER SHIELD LOWER (WCP)	Cracked	90.00 F	*90.00 F
22	5		*FRONT LH FENDER INNER SHIELD RIVET (WCP)	Necessary	15.00 F	*15.00 F
23	5		*FRONT LH FENDER INNER SHIELD CLIP (WCP)	Necessary	10.00 F	*10.00 F
24	1		*LH HEADLAMP (WCP)	Cracked	2,950.00 F	*2,950.00 F
25	1		*LH HEADLAMP POWER MODULE (WCP)	Serviceable	370.00 F	*- F
26	1		*LH HEADLAMP LED CONTROL MODULE (WCP)	Serviceable	580.00 F	*- F
27	1		*LH HEADLAMP BREATHER HOSE (WCP)	Serviceable	66.00 F	*- F
Report was unsubmitted during this print-out.						

7/18/23, 11:16 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*LH HEADLAMP SEALFRAME (WCP)	Serviceable	82.00 F	*- F
29	1		*FRONT GRILLE (WCP)	Cracked	470.00 F	*470.00 F
30	1		*FRONT NO.PLATE WITH BOX	Dented	50.00 FS	*25.00 FS
Supplementary #1						
31	1		*FRONT SUPPORT CENTRE TRIM	Cracked	140.00 F	*140.00 F
F=Franchise part. S=SpcNett.						
Sub Total (S\$)					8,394.00	5,776.00
+ Margin on L,N Items 10.00/10.00% (S\$)					834.40	575.10
Total Parts (S\$)					9,228.40	6,351.10
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REWIRE DAMAGED PARTS & REFOCUS HEADLAMP BEAM,DIAGNOS & RESET HEADLAMP SYSTEM	New	150.00	60.00
2	TO PUTTY AND SPRAY REPLACED PARTS	New	800.00	600.00
3	TO REMOVE,CUT OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ABOVE PARTS	New	800.00	500.00
Gross Labour Cost (S\$)			1,750.00	1,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >