

ASS. REC. BY:

REF:

AIS / 23005214Kp

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

04 days

Res.: Yes or No

Lum Sum: _____

1.8.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

SNG 9725E

Yr Regn: _____

09.22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

NIS

Seren

C.C. _____

1198

Colour _____

m.d. Blue

A/C: _____

Insured / Std / NI / NA

Sp. Reading _____

82840

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

JNIEBAC277 0001480

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / Rim or

Tyre Size: _____

F: _____

ilink

195 700R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Reac

Front

Rear

R/Bal. _____

9

mm

R/Bal. _____

P

mm

L/Bal. _____

9

mm

L/Bal. _____

P

mm

D.O.A. _____

12/5/23

D.O.I. _____

24/5/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

9/6 8 4273.09 Cuh

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation

S - RS - SI

Factors

Others

Add Fee: _____

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TPVehicle No. : SNG9725EMake & Model : NISSAN SERENAYear of Manufacture : 2022

Chassis No. : _____

Engine No. : _____

Policy No. : _____

Time of Accident : _____

Ins Company : Allianz Insurance

Excess : _____

Date of Accident : 12/05/2023

Suggested Days of Repair : _____

In-house Vehicle Assessor

Case Owner : _____

Signature : _____

Repair EstimatesParts (a) Cost / List Price Items \$ 4,629.00Plus/Less 10% \$ 462.90Total of Cost / List \$ 4,166.10(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ 50.00Total Parts Cost (Appendix A) \$ 4,216.10Labour (Appendix B) \$ 1,370.00Total Repair Cost \$ 5,586.10

Contact No
Operation
 KELVIN SU
 TEL: 9786 4236
 E: kelvinsukwen@cdge.com.sg

JOHARI
 TEL: 972103705
 E: joharibh@sparkcarcare.com

SUN PIN
 TEL: 9728 8916
 E: oisunpin@cdge.com.sg

*Not Authorized
 Penny B. Giam*

\$ 4273.09

The above total will be subjected to 8% G.S.T.

Name of Surveyor : KennethCompany : CLCSurvey conducted on : 24/5/23 at _____Remarks By Surveyor(a) The repair of this vehicle is authorized / is not authorized until further notice.(b) Recommended Days of Repair : 04 day(s)(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : LeDate: 24/5/23

Spark Car Care
ComfortDelGro Engineering Pte Ltd
 205 Braddell Road S (579701)
 Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No : SNG9725E Case Owner : 0

Make & Model : NISSAN SERENA Year Manufacture : 2022

Chassis No : 0 Engine No : 0

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	REAR BUMPER <i>1527-10</i>	1	<i>Bu</i>	\$ 1,575.00			☒
2	REAR BUMPER LH RETAINER	1	<i>1u</i>	\$ 38.00			☒
3	REAR BUMPER RH RETAINER	1	<i>1u</i>	\$ 38.00			☒
4	REVERSE SENSOR CENTER LH	1	<i>1u</i>	\$ 258.00			☒
5	REVERSE SENSOR CENTER RH	1	<i>1u</i>	\$ 258.00			☒
6	REVERSE SENSOR HOLDER	4	<i>1u</i>	\$ 360.00			☒
7	TAILGATE <i>1881-00</i>	1	<i>1u</i>	\$ 1,940.00			☒
8	TAILGATE EMBLEM "HIGHWAY STAR"	1	<i>1u</i>	\$ 57.00			☒
9	TAILGATE EMBLE "E-POWER"	1	<i>1u</i>	\$ 105.00			☒
10	REAR BUMPER CLIPS	1			<i>1u</i> \$ 50.00		☒
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27	0	1					
28	0	1					
29	0	1					
30	0	1					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax: 62815767

Vehicle No.	: <u>SNG9725E</u>	Case Owner	: <u>0</u>
Make & Model	: <u>NISSAN SERENA</u>	Year of Manufacture	: <u>2022</u>

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.