

205 Braddell Road S(579701)

| 200 2.4440 1.044 0(0  |   | REPAIR ESTIMATES  |
|---|---|---|
| Our Ref:  | ACCIDENT KE   | ILFAIR ESTIMATES  |
| Ins Company : Allianz I  Excess :  Date of Accident :12/05  Suggested Days of Repair :  Repair Estimates                    | 5/2023  | Vehicle No. : SNG9725E  Make & Model : NISSAN SERENA  Year of Manufacture : 2022  Chassis No. :   |
| Total of Cost / List  (b) Nett Price Items  Less  Total of Nett Item  (c) Special Nett Items  Total Parts Cost (Appendix A) | \$ 462.90<br>\$ 4,166.10<br>\$ -<br>\$ 50.00<br>\$ 4,216.10<br>\$ 1,370.00<br>\$ 5,586.10 | Contact No Operation KELVIN SU TEL: 9786 4236 E: kelvinsukwen@cdge.com.sg  JOHARI TEL: 972103705 E: joharibh@sparkcarcare.com  SUN PIN TEL: 9728 8916 E: oisunpin@cdge.com.sg  Menny Byne |
| Name of Surveyor  | :   | Kennorh   |
|   |   |   |

| Name of Surveyor  Company  Survey conducted on   | Kennorh  |
|--|--|
| Remarks By Surveyor  (a) The repair of this vehicle is authors  (b) Recommended Days of Repair  (c) Resurvey | Horized / is not authorized until further notice.  :day(s) : Required / Not Required |
| (d) Excess (e) Signature of surveyor   | :\$<br>:   |

## **Spark Car Care**

ComfortDelGro Engineering Pte Ltd 205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62815767

Type of Claim

: <u>TP</u>

|       | _  | -       |
|-------|----|---------|
| <br>- | Ра | $\pi s$ |
|       |    |         |

rder By

| Vehicle No   | : SNG9725E      | Case Owner       | : <u>0</u> |
|--------------|-----------------|------------------|------------|
| Make & Model | : NISSAN SERENA | Year Manufacture | : 2022     |
| chassis No   | : <u>0</u>      | Engine No        | : <u>0</u> |
| ales Order   | :               | Supplier         | i          |

| Part Description                        | QTY         | Cost<br>Price   |           | List<br>Price | Nett<br>Price  | S/N         |               | position<br>rveyor |          |
|---|-------------|-----------------|-----------|---------------|--|-------------|---------------|--------------------|----------|
| REAR BUMPER                             | 1           | Ben             | \$        | 1,575.00      |  |             |               | ×                  | 7        |
| REAR BUMPER LH RETAINER                 | 1           | In              | \$        | 38.00         |  |             |               | <u> </u>           |          |
| REAR BUMPER RH RETAINER                 | 1           | In              | \$        | 38.00         |  |             | -             | X                  | V        |
| REVERSE SENSOR CENTER LH                | 1           | رم              | \$        | 258.00        |  |             | -             | X                  |          |
| REVERSE SENSOR CENTER RH                | 1           | h               | \$        | 258.00        |  |             |               | X                  | ,        |
| REVERSE SENSOR HOLDER                   | 4           | In              | \$        | 360.00        | L  | <u> </u>    |               | <del></del>        | <u> </u> |
| TAILGATE                                | 1           | By              | \$        | 1,940.00      |  | <del></del> |               | <u> </u>           | _        |
| TAILGATE TAILGATE EMBLEM "HIGHWAY STAR" | 1           | M               | \$        | 57.00         |  | -           | -             |                    | _        |
| TAILGATE EMBLE "E-POWER"                | 1           | M               | \$        | 105.00        | -  | -           |               |                    | _        |
| REAR BUMPER CLIPS                       | 1           |                 |           | 41.0          | Ne   | \$          | 50.00         |                    |          |
|   | 1 20        |                 |           | 10.5          | 0:   | -           |               |                    | -        |
|   |             | and the same of |           | 1             |  | +-          |               |                    | 1        |
|   |             | Figs.           |           |               |  | 1           |               |                    |          |
|   |             | 3-              | Γ         | 4             |  | 1           | tifu          |                    |          |
|   |             |                 | T         | LKK Auto      | Consultants he   | ince no     | outy          | $\Box$             |          |
|   |             |                 | $\forall$ | the Repai     | ALBL OF THE TOHON  | av paintin  | ing           |                    |          |
|   | 5.5         |                 | $\sqcap$  |               |  |             |               |                    |          |
|   |             |                 | +         | Parts price   | ices are subject to c  | con irma    | Prejudice" ha | ss                 |          |
|   | <del></del> |                 | +         | Third par     | arty survey is on a  |             | 4             | 1                  |          |
|   |             | 4 1 2 20        | +         | • No illeg    | pal modification(s) is<br>ementary item(s) musecr o final approval | st Lu res   | surveyed and  | 1                  | 1        |
|   |             |                 | 1         | • Supple      | ICI to final approva   | I from In:  | surance Con   | ipariy             | +        |
|   | , I         |                 | +         | 1             |  | 1           |               | +                  | +        |
|   |             |                 | $\perp$   |               | riedged by Repairer  | 1 1         | -             | +                  | +        |
|   |             | LE              |           | Signatur      | ire:   |             |               | 4                  | 1        |
|   | 9 , 1       |                 |           | Date:         | -  | 一           |               |                    |          |
|   |             |                 | 十         |               | 7  |             |               |                    |          |
|   |             | <del></del>     | +         |               |  | +           |               |                    |          |
|   |             |                 | +         |               |  | +           |               | +                  |          |
|   | 1           |                 | +         |               |  | +           |               | +                  | _        |
|   | 1           |                 | 1         |               |  | 1           |               | +                  | _        |
|   | 1           |                 |           |               |  |             |               |                    | _        |
|   | 1           |                 | +         |               |  |             |               |                    |          |

: If any of the quoted parts are recommended to be repaired, then an additional labour charge be charged accordingly under supplementary.

## Spark Car Care

## ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax: 62815767

Labour

| Vehicle No.  | : | SNG9725E      | Case Owner          | ; 0  |  |
|--------------|---|---------------|---------------------|------|--|
| Make & Model | : | NISSAN SERENA | Year of Manufacture | 2022 |  |

| Ke       | & Model:NISSAN SERENA Year of Manufacture  | 2022              |                   |  |  |
|----------|--|-------------------|-------------------|--|--|
| No       | Labour Description   | Esimated<br>Price | Adjusted<br>Price |  |  |
|          | To knock & straighten on accident area, to remove & refit Rear damage parts.   | \$600.00          | 4001              |  |  |
|          | To putty & respray on Rear damage area.  | \$600.00          | 4401              |  |  |
| 1        | o check wiring & install reverse sensor.   | \$50.00           | ~                 |  |  |
| 1        | o remove & refit rear windscreen.  | \$120.00          | ~                 |  |  |
| 1        | - Carlotte C |                   | 1                 |  |  |
| $\pm$    |  |                   |                   |  |  |
| 1        |  |                   |                   |  |  |
| #        |  | 1 1 1 1 1         |                   |  |  |
| $\pm$    |  |                   |                   |  |  |
| +        |  |                   |                   |  |  |
| 1        |  |                   |                   |  |  |
| $\pm$    |  |                   |                   |  |  |
| +        |  |                   |                   |  |  |
|          |  |                   |                   |  |  |
|          |  |                   |                   |  |  |
|          |  |                   |                   |  |  |
|          |  |                   |                   |  |  |
| -        |  |                   |                   |  |  |
| $\vdash$ |  |                   |                   |  |  |

lote: The above estimate of repair is based on visual assessment of the external affected areas. Any dditional damages observed during the course of repair will be quote accordingly as a supplementary.