



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNH 264Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOT COVER	BADLY DENTED	1,028.40	1,028.40
1	REAR BOOT EMBLEM (VEZEL)	SCRATCHED	49.20	49.20
1	REAR BOOT COVER OUTER COVER	CUT / CRACKED	789.20	789.20
1	REAR BOOT LAMP LH	CRACKED	400.20	400.20
1	REAR BUMPER FASCIA	DISTORTED	688.20	688.20
1	SET REAR BUMPER CLIPS	NOT NECESSARY	38.00	-
2	REAR BUMPER SIDE RETAINER L&R @\$29.20	NOT NECESSARY	58.40	-
1	REAR BUMPER LOWER GARNISH	TO REPAIR SEE LABOUR	829.15	-
1	REAR BUMPER LOWER LIP	TO REPAIR SEE LABOUR	290.40	-
1	TAIL LAMP LH	BROKEN	478.20	478.20
2	REAR FENDER ARCH GARNISH WITH CLIPS L&R @ \$134.20	NOT NECESSARY	268.40	-
1	REAR WINDSCREEN GLASS	NOT NECESSARY	1,118.79	-
1	REAR WINDSCREEN MOULDING	NECESSARY	153.20	153.20
	LESS 20% DISCOUNT		-	-717.32
			6,189.74	2,869.28
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	40.00
4	REAR BUMPER SENSOR @\$305.20 (SN)	SERVICEABLE	1,220.80	-
			1,280.80	40.00
<u>LABOUR</u>				
	CUT OUT, RENEW, KNOCKING & WELDING, REAR BOOT COVER, REAR END PANEL, REMOVE & INSTALL ALL DAMAGE PARTS, STRAIGHTEN & RE-ALIGN BODY. INCLUSIVE OF THE REPAIR OF REAR BUMPER LOWER GARNISH AND REAR BUMPER LOWER LIP.		980.00	600.00
	TUFF-KOTE ON DAMAGE PARTS.		40.00	30.00
	SPRAY PAINTING ON DAMAGE PARTS.		1,280.00	950.00
	REMOVE & REFIX REAR BUMPER SENSOR.		80.00	40.00
	REMOVE & REFIX REAR WINDSCREEN GLASS.		140.00	120.00

Report Ref No. CS/INC23005218/Uqp3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	CHECK ALL LIGHTING AFTER REPAIRS.		35.00	20.00
			2,555.00	1,760.00
GRAND TOTAL			10,025.54	4,669.28
RECOMMENDED COST OF REPAIRS (CONFIRMED)				4,669.28

Report Ref No. CS/INC23005218/Uqp3e2

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.