



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 4849E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOT LID LOGO EMBLEM	NECESSARY	41.00	41.00
1	REAR BOOT LID ATTRAGE EMBLEM	NECESSARY	35.00	35.00
1	REAR BOOT LID LOCK	NOT NECESSARY	206.00	-
1	REAR BOOT LID WEATHER STRIP	TORN	148.00	148.00
1	REAR BUMPER	DEFORMED	708.00	708.00
2	REAR BUMPER SIDE RETAINER LH/RH @\$26.00	NOT NECESSARY	52.00	-
1	REAR BUMPER REFLECTOR RH	NOT NECESSARY	20.00	-
1	REAR END PANEL	NOT NECESSARY	402.00	-
1	REAR END PANEL INNER TOP GARNISH	NOT NECESSARY	62.00	-
	LESS 10% DISCOUNT		-167.40	-93.20
			1,506.60	838.80
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	NOT WORKING	280.00	200.00
1	SET REAR END PANEL INNER TOP GARNISH CLIPS (SN)	NOT NECESSARY	50.00	-
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	80.00	-
			470.00	230.00
<u>LABOUR</u>				
	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION.		800.00	500.00
	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA.		600.00	400.00
	TO APPLY ANTI-RUST & TUFF KOTE.	NOT NECESSARY	120.00	-
	TO PERFORM LIGHTING & WIRING CHECK.	NOT NECESSARY	150.00	-
	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING.		150.00	30.00
	TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR.		250.00	60.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION.	NOT NECESSARY	100.00	-
			2,170.00	990.00
GRAND TOTAL			4,146.60	2,058.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,600.00

Report Ref No. CS/INC23005219/Tvp3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.