



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1681L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER UPPER	TO REPAIR SEE LABOUR	535.00	-
1	REAR BUMPER LOWER	CUT	554.00	554.00
1	REAR BUMPER O/S MOULDING	CUT	15.00	15.00
1	REAR O/S FENDER GARNISH	CRACKED	144.00	144.00
1	REAR O/S FENDER INNER SHIELD	NOT NECESSARY	255.00	-
1	REAR BUMPER O/S REFLECTOR	NOT NECESSARY	178.00	-
1	REAR BUMPER O/S REFLECTOR COVER	NOT NECESSARY	43.00	-
2	REAR BUMPER SIDE BRACKET N/S & O/S @\$25.00	NOT NECESSARY	50.00	-
1	REAR O/S DOOR	TO REPAIR SEE LABOUR	1,542.00	-
1	REAR O/S RIM	CUT	956.00	956.00
	LESS 10% DISCOUNT		-427.20	-166.90
			3,844.80	1,502.10
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	58.00	30.00
1	SET REAR O/S FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	58.00	-
1	REAR O/S FENDER STICKER (SN)	NECESSARY	60.00	60.00
1	SUNDRY (SN)	NOT NECESSARY	50.00	-
			226.00	90.00
<u>LABOUR</u>				
	CHECK WHEEL ALIGNMENT.		50.00	50.00
	TO DISMANTLE AND REFIT REVERSE SENSOR INTO NEW BUMPER.		120.00	30.00
	TO DISMANTLE AND REFIT REAR O/S DOOR INNER COMPONENT INTO NEW SHELL DOOR.		150.00	60.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. INCLUDING TO KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE OF THE REAR O/S FENDER ETC. INCLUSIVE OF THE REPAIR OF REAR BUMPER UPPER AND REAR O/S DOOR.		650.00	500.00
	TO PUTTY AND SPRAY PAINTING ON THE REAR BUMPER UPPER, REAR BUMPER LOWER, REAR O/S FENDER, REAR O/S DOOR.		900.00	600.00

Report Ref No. CS/INC23005220/Tnp3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		150.00	30.00
			2,020.00	1,270.00
	GRAND TOTAL		6,090.80	2,862.10
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			2,862.10

Report Ref No. CS/INC23005220/Tnp3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.