

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23005223/UVP3Q2**Date:** 31/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00183922200		
Claimant Vehicle No :	GBJ5218E	Insured Vehicle No :	SMP8668H		
Date of Loss:	28/04/2023	Nature of Claim:	TP	Claim No:	SNM23D203665/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ5218E	Engine No:	RZ4E10K681
Make & Model:	ISUZU NHR87AUE4AA, 1.9 D (M)	Chassis No:	JAANHR87EK7100123
Reg. Date:	15/05/2019 (Man. Year: 2019)	Odometer:	208070 km
Colour:	White		
Engine Capacity:	1898 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	155 R13 (D)
Front Left Side:	RIVO 6 mm	Rear Left Side:	RIVO 6/6 mm
Front Right Side:	RIVO 6 mm	Rear Right Side:	RIVO 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,100.00	0.00	1,100.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,280.00	500.00	780.00	60.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,380.00	500.00	1,880.00	78.99
+ GST 8.00/8.00% (S\$)	190.40	40.00	150.40	78.99
Nett Amount (S\$)	2,570.40	540.00	2,030.40	78.99

INSPECTION

Date of Assignment:	23/05/2023		1 KAKI BUKIT AVE 6
Date Inspected:	23/05/2023	Inspected At:	#01-73, AUTOBAY @KAKI BUKIT SINGAPORE 417883
Estimated Period of Repair:	1.0 days		Repairer: SPEEDWERKZ PTE LTD (HQ)

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 30 May 2023)	
Parts:	N/A	ISUZU NHR87AUE4AA 1.9 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ5218E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*N/S STEP BRACKET	Repair	800.00 FS	*- FS
2	1		*REAR MUDGUARD N/S	Not Necessary	300.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					1,100.00	0.00
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	0.00
2	TO SPRAY RUST PROOFING	New	50.00	0.00
3	TO CONDUCT WHEEL ALIGNMENT	New	80.00	0.00
4	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	600.00	300.00
5	TO PUTTY & SPRAY PAINTING	New	500.00	200.00
Gross Labour Cost (S\$)			1,280.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >