



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBS 6516R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	<b><u>REPLACEMENT OF PARTS</u></b>	CRACKED		
	FRONT LOWER BUMPER		1,516.00	1,516.00
	LESS 10% DISCOUNT		-	-151.60
			1,516.00	1,364.40
	<b><u>LABOUR</u></b>			
	REPAIR NSF CORNER BUMPER.		100.00	100.00
	LABOUR FOR REMOVAL AND REPLACEMENT.		120.00	120.00
	PAINING OF REPLACED AND REPAIR PARTS.		480.00	300.00
			700.00	520.00
<b>GRAND TOTAL</b>			<b>2,216.00</b>	<b>1,884.40</b>
<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>				<b>1,884.40</b>

Report Ref No. CS/INC23005227/Tqp3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.